

Register entry, as of 27 October 2026

Listed for sale

Record ID b059527dd9b3

2010 MINI Cooper

1.6 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMW MF3C5 9 A T Z23017

WMI 1-3

MINI · BMW AG

DESCRIPTOR 4-8

Cooper · 1.6 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Oxford

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	1.6 L, 4 cylinders
Make	MINI	Fuel	Gasoline
Model	Cooper	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Hatchback	Plant	Oxford, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mini/cooper/2010

5 recalls listed by Transport Canada for this model year

Electrical	2023281	11 May 2023
Issue: On certain vehicles, the footwell module (FRM) may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: BMW will notify owners by mail. The corrective actions for this recall are under development. BMW advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.		
Electrical	2018544	3 Oct 2018
On certain vehicles, the footwell module (FRM3) may become contaminated by a mixture of salt and moisture which could lead to corrosion over time. This could cause a short circuit, resulting in overheating of the module that could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect the footwell module, and replace if necessary. A protective film will be also installed over the module. Note: Owners are advised to park the vehicle outdoors until the recall repairs have been completed.		
Electrical	2012008	11 Jan 2012
On certain vehicles, the auxiliary water pump (which cools the turbocharger after the engine is turned OFF) can overheat and fail. This could result in a vehicle fire causing property damage and/or personal injury. Correction: Dealers will replace the auxiliary water pump. Note: Owners are advised to park the vehicle outdoors until the remedy is applied.		
Label	2010382	3 Nov 2010
On certain vehicles, the "B" pillar National Safety Mark label is distorted as a result of a printing error. This situation does not pose a risk to highway safety. Correction: Due to the inconsequential nature of this non-compliance, no action will be taken.		



Label

2009358 17 Dec 2009

On certain vehicles, the tire information label may have the wrong tire size or the wrong tire pressure. Correction: Dealers will install new tire information labels on affected vehicles.

Listed for the model year, not checked against your VIN. MINI confirms which apply.
Check your VIN with MINI Canada or call a MINI dealer with your VIN.
crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$2,499^[5], \$4,773 under the median of \$7,272^[4].



Lowest ask	\$2,499
Middle half	\$6,961 – \$8,225
Median ask	\$7,272
This car	\$2,499

Same model year · 6 live listings · as of 27 Oct 2026

OTHER 2010 MINI COOPER LISTINGS [5]

London, ON · 115,436 km	\$8,495
Surrey, BC · 112,000 km	\$6,995

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Oxford, United Kingdom
17 Dec 2009	Transport Canada recall 2009358 ^[2] Issued for the model year · Label
3 Nov 2010	Transport Canada recall 2010382 ^[2] Issued for the model year · Label
11 Jan 2012	Transport Canada recall 2012008 ^[2] Issued for the model year · Electrical
3 Oct 2018	Transport Canada recall 2018544 ^[2] Issued for the model year · Electrical
11 May 2023	Transport Canada recall 2023281 ^[2] Issued for the model year · Electrical
19 Jan 2026	Listed for sale, St. Catharines, ON ^[5] Teka Cars · asking \$2,499
24 Oct 2026	Listing last updated ^[5] asking \$2,499



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 6 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

