Register entry, as of 27 October 2026 Listed for sale Record ID de44792ff35c

2008 MINI Cooper

1.6 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMW	MF735	3	8	T	T89188
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
MINI · BMW AG	Cooper · 1.6 L	Computes	2008	Oxford	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	1.6 L, 4 cylinders
Make	MINI	Fuel	Gasoline
Model	Cooper	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Hatchback	Plant	Oxford, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mini/cooper/2008

4 recalls listed by Transport Canada for this model year

Electrical — 2023281 — 11 May 2023

Issue: On certain vehicles, the footwell module (FRM) may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: BMW will notify owners by mail. The corrective actions for this recall are under development. BMW advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Electrical — 2018544 — 3 Oct 2018

On certain vehicles, the footwell module (FRM3) may become contaminated by a mixture of salt and moisture which could lead to corrosion over time. This could cause a short circuit, resulting in overheating of the module that could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect the footwell module, and replace if necessary. A protective film will be also installed over the module. Note: Owners are advised to park the vehicle outdoors until the recall repairs have been completed.

Electrical — 2012008 — 11 Jan 2012

On certain vehicles, the auxiliary water pump (which cools the turbocharger after the engine is turned OFF) can overheat and fail. This could result in a vehicle fire causing property damage and/or personal injury. Correction: Dealers will replace the auxiliary water pump. Note: Owners are advised to park the vehicle outdoors until the remedy is applied.

Other — 2009028 — 29 Jan 2009

On certain vehicles, the centrally-located tailpipe extension protrudes slightly beyond the rear bumper. As a consequence, it is possible for inadvertent contact with a person's leg. It the tailpipe is hot during contact, a burn could occur. Correction: Dealers will replace the tailpipe extension with a new, shortened version.

> Listed for the model year, not checked against your VIN. MINI confirms which apply.
> Check your VIN with MINI Canada or call a MINI dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,500[5], $1,501 over the median of $4,999[4].

Lowest ask	$1,500
Middle half	$3,250 – $5,750
Median ask	$4,999
This car	$6,500

Same model year · 3 live listings · as of 27 Oct 2026

OTHER 2008 MINI COOPER LISTINGS [5]

Ajax, ON · 176,802 km	$6,995
Nobleton, ON · 140,099 km	$1,500

§4 EVENTS

2008	Model year 2008[1] Assembly plant Oxford, United Kingdom
29 Jan 2009	Transport Canada recall 2009028[2] Issued for the model year · Other
11 Jan 2012	Transport Canada recall 2012008[2] Issued for the model year · Electrical
3 Oct 2018	Transport Canada recall 2018544[2] Issued for the model year · Electrical
11 May 2023	Transport Canada recall 2023281[2] Issued for the model year · Electrical
24 Nov 2025	Listed for sale, Mississauga, ON[5] VAULT MOTORS · asking $6,500
25 Oct 2026	Listing last updated[5] asking $6,500

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.