Register entry, as of 27 November 2026 Listed for sale Record ID 056f5e837ff2

2003 MINI Cooper

4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMW	RC334	2	3	T	E13510
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
MINI · BMW AG	Cooper · 4 cylinders	Computes	2003	Oxford	Build sequence

§1 IDENTITY [1]

Model year	2003	Engine	4 cylinders
Make	MINI	Fuel	Gasoline
Model	Cooper	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Hatchback	Plant	Oxford, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mini/cooper/2003

2 recalls listed by Transport Canada for this model year

Steering

2012029 30 Jan 2012

On certain vehicles, the electro-hydraulic power steering pump could fail temporarily or permanently due to problems with the electronics that control the function of the pump, a failure of the pump cooling fan, or a loss of power to the pump. A vehicle experiencing a loss of steering power assist would revert to a manual steering mode which would require greater driver effort, especially at low vehicle speeds. Nevertheless, a loss of steering power assist could ultimately result in a crash causing property damage and/or personal injury. Correction: The electro-hydraulic power steering pump, as well as the pump cooling fan, will be subject to special extended warranty coverage of 12 years or 200,000 km from first in-service date of the vehicle.

Suspension

2003055 7 Mar 2003

On certain vehicles, the head of the screw securing the rear struts to the chassis may tear off. The remaining portion of the screw (stud, or shaft) will still hold the strut in place. However, if left unattended over a longer period of time, and depending on driving conditions, the stud/shaft may break. If this occurred, the chassis would lean directly on the tire, diminishing the driver's ability to control the vehicle. Depending on traffic conditions and the driver's reactions, this could lead to a crash. Correction: Dealer will replace the lower screw connection of the rear struts.

> Listed for the model year, not checked against your VIN. MINI confirms which apply.
> Check your VIN with MINI Canada or call a MINI dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,888[5], $3,554 under the median of $8,442[4].



Lowest ask	$4,888
Middle half	$6,665 – $10,218
Median ask	$8,442
This car	$4,888

Same model year · 2 live listings · as of 27 Nov 2026

OTHER 2003 MINI COOPER LISTINGS [5]

Saskatoon, SK · 44,464 km	$11,995

§4 EVENTS

2003	Model year 2003[1] Assembly plant Oxford, United Kingdom
7 Mar 2003	Transport Canada recall 2003055[2] Issued for the model year · Suspension
30 Jan 2012	Transport Canada recall 2012029[2] Issued for the model year · Steering
31 Oct 2026	Listed for sale, Langley, BC[5] Jaguar Landrover Langley · asking $4,888
27 Nov 2026	Listing last updated[5] asking $4,888

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 27 Nov 2026
[5] Live public dealer listings on Cardog, as of 27 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.