

Register entry, as of 26 October 2026

Listed for sale

Record ID b0dcf1e393ca

1985 Porsche 944 S

2.5 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0 AA094 7 F N 473087

WMI 1-3

Dr. Ing. H.C.F. Porsche Ag

DESCRIPTOR 4-8

944 · 2.5 L

CHECK 9

Computes

YEAR 10

1985

PLANT 11

Neckarsuim

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	1985	Engine	2.5 L, 4 cylinders
Make	Porsche	Fuel	Gasoline
Model	944	Drive	Not in the decode
Trim	S	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Coupe	Plant	Neckarsuim, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/944/1985

3 recalls listed by Transport Canada for this model year

Fuel system 1990051 4 Apr 1990

THE SHORT SECTION OF HIGH PRESSURE FUEL HOSE BETWEEN THE FUEL RAIL AND THE FUEL PRESSURE REGULATOR, WHICH RUNS ALONGSIDE THE INTAKE MANIFOLD, MAY BE SUBJECT TO HARDENING. IN THE EVENT THAT THIS LINE DOES HARDEN, FUEL LEAKS COULD DEVELOP BETWEEN THE HOSE AND METAL PIPE FITTINGS. LEAKING FUEL COULD IGNITE ON THE HOT EXHAUST SYSTEM AND LEAD TO AN ENGINE COMPARTMENT FIRE. CORRECTION: FUEL HOSE WILL BE REPLACED ON 924S, 944 AND 944 TURBO VEHICLES AND THE FUEL HOSE AND FUEL RAIL WILL BE REPLACED ON 944S VEHICLES.

Not entered 1985040 12 Apr 1985

THE FUEL SUPPLY HOSE TO THE PRESSURE DAMPER IN THE ENGINE COMPARTMENT MAY DEVELOP A LEAK BETWEEN THE FLEX HOSE AND THE THREADED CONNECTOR DUE TO IMPROPER CRIMPING OF THE FITTING. THIS WILL CAUSE THE FUEL PRESSURE IN THE INJECTION SYSTEM TO DROP, RESULTING IN ENGINE STALLING. A STALLED VEHICLE COULD POSE A THREAT TO TRAFFIC SAFETY.

Not entered 1985026 5 Mar 1985

VEHICLES WITH CRUISE CONTROL. UNDER CERTAIN CONDITIONS THERE COULD BE INSUFFICIENT CLEARANCE BETWEEN THE METAL BUSHING AND THE SHAFT OF THE CRUISE CONTROL LINKAGE. ALSO, THE LINKAGE POINTS WERE NOT LUBRICATED DURING ASSEMBLY. WITH THE CRUISE CONTROL SWITCHED ON, THE CONTOL LINKAGE COULD BIND CAUSING THE ACCELERATOR PEDAL TO STICK ON THE DEPRESSED POSITION. THIS COULD RESULT IN LOSS OF CONTROL AND VEHICLE CRASH.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.


No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing. [3]



§3 VALUE [4]

This car asks \$8,000^[5], the median^[4].



Lowest ask	\$8,000
Middle half	\$8,000 – \$8,000
Median ask	\$8,000
This car	\$8,000

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

1985	Model year 1985 ^[1] Assembly plant Neckarsuim, Germany
5 Mar 1985	Transport Canada recall 1985026 ^[2] Issued for the model year · Not entered
12 Apr 1985	Transport Canada recall 1985040 ^[2] Issued for the model year · Not entered
4 Apr 1990	Transport Canada recall 1990051 ^[2] Issued for the model year · Fuel system
25 Oct 2026	Listed for sale, Calgary, AB ^[5] JJ Auto Sales & Services Ltd · asking \$8,000

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 26 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

