Register entry, as of 28 October 2026 Listed for sale Record ID a3c5d14f22e4

2018 Porsche Panamera Base / 4

3.0 L, 6 cylinders · RWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	AA2A7	9	J	L	112093
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Panamera · 3.0 L	Computes	2018	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Panamera	Drive	RWD
Trim	Base / 4	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sedan	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/panamera/2018

7 recalls listed by Transport Canada for this model year

Heater and defroster

2023024 26 Jan 2023

Issue: On certain vehicles, water could leak into the external coolant pump for the climate control system and cause a short circuit. If this happens, the pump and wiring could overheat and melt. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and instruct you to bring your vehicle to a dealership to replace the external coolant pump. Additionally, the connections for the pump will be inspected and replaced, if necessary.

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Lights and instruments

2019522 16 Oct 2019

Issue: On certain vehicles, the red brake wear warning light may not come on when the brake pads require replacement. This can happen when the instrument cluster display is set to the Map or Night Vision mode. Canadian regulations require the warning indicator to stay on when the brakes are worn. Note: This recall replaces Transport Canada recall 2019-078. Vehicles that were repaired under that recall also require this repair. Safety Risk: Driving a vehicle with brakes that are worn out could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct them to take their vehicle to a dealer to update the instrument cluster software.

Electrical

2019115 6 Mar 2019

Issue: On certain cars, an electronic control unit may fail. If this happens, it could cause various error messages to display on the instrument cluster. Some vehicle systems may not work properly. It could also cause drivability problems or make the car hard to start. Safety Risk: Drivability problems, including a sudden loss of engine power, could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to bring the vehicle to a dealership to have the gateway control unit replaced.

Brakes

2019078 20 Feb 2019

Issue: On certain vehicles, the red brake wear warning light does not come on when the brake pads are worn out. This could increase the risk of the vehicle being driven with worn out brake pads. Note: A yellow warning message will be displayed if the brake pads wear out. Note: This recall is superseded by recall 2019522. Please see recall 2019522 for more information. Safety Risk: Driving a vehicle with worn out brake pads could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the instrument cluster software.

Steering

2018722 20 Dec 2018

On certain vehicles, a fault in the power steering system may cause an intermittent loss of steering assist without warning. A loss of power assist would result in a sudden, unexpected increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will reprogram the power steering control unit software.

1 more on the model-year record, cardog.app/tools/recalls/porsche/panamera/2018

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $46,995[5], $20,387 under the median of $67,382[4].

Lowest ask	$48,900
Middle half	$53,314 – $72,245
Median ask	$67,382
This car	$46,995

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2018 PORSCHE PANAMERA LISTINGS [5]

Sainte-Rose, QC · 118,000 km	$69,995
Concord, ON · 98,000 km	$48,900
Mont-Royal, QC · 55,000 km	$64,770
Richmond, BC · 113,139 km	$49,495

§4 EVENTS

2018	Model year 2018[1] Assembly plant Leipzig, Germany
13 Jun 2018	Transport Canada recall 2018313[2] Issued for the model year · Suspension

20 Dec 2018	Transport Canada recall 2018722[2] Issued for the model year · Steering
20 Feb 2019	Transport Canada recall 2019078[2] Issued for the model year · Brakes
6 Mar 2019	Transport Canada recall 2019115[2] Issued for the model year · Electrical
16 Oct 2019	Transport Canada recall 2019522[2] Issued for the model year · Lights and instruments
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
26 Jan 2023	Transport Canada recall 2023024[2] Issued for the model year · Heater and defroster
4 Jun 2026	Listed for sale, Vaughan, ON[5] AUTOLINKS · asking $46,995
27 Oct 2026	Listing last updated[5] asking $46,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.