Register entry, as of 29 October 2026 Listed for sale Record ID c14e0767a881

2014 Porsche Panamera Base (2WD), 4 (4WD)

3.6 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	AA2A7	X	E	L	007729
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Panamera · 3.6 L	Computes	2014	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.6 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Panamera	Drive	Not in the decode
Trim	Base (2WD), 4 (4WD)	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sedan	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/panamera/2014

4 recalls listed by Transport Canada for this model year

Other

2026301 17 Jun 2026

Issue: On certain vehicles, the immobilizer system may not meet certain requirements of Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Porsche has made changes to ensure that all new vehicles meet Canadian regulations.

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Powertrain

2019290 12 Jun 2019

Issue: On certain vehicles, the transmission shifter could detach from the transmission. This could cause the transmission not to shift gears when the shifter is moved. As a result, the transmission could be in a different gear than the gear shifter indicates. If a driver attempts to exit the vehicle while the transmission is not in Park, and the parking brake is not applied, the vehicle could move suddenly. Safety Risk: Sudden and unexpected movement of the vehicle could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct them to take their vehicle to a dealer to replace the shifter cable bushing. Owners are reminded to use the parking brake anytime the vehicle is parked.

Electrical

2019200 25 Apr 2019

Issue: On certain cars, water could leak into the air conditioning blower control unit. Over time, this could cause a short circuit that could cause it to melt or burn. This could happen while driving or after the vehicle is parked and shut off. Safety Risk: A short circuit in the blower control unit could create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and advise them what to do. When a remedy is available, owners will be requested to bring their car to a dealership for repair. Owners are advised to park their car outdoors until the recall repairs have been completed.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $29,999[5], $4 over the median of $29,995[4].

Lowest ask	$22,995
Middle half	$29,485 – $32,450
Median ask	$29,995
This car	$29,999

Same model year · 7 live listings · as of 29 Oct 2026

OTHER 2014 PORSCHE PANAMERA LISTINGS [5]

Calgary, AB · 121,245 km	$22,995
Richmond, BC · 72,731 km	$28,995
Vaudreuil-Dorion, QC · 159,332 km	$39,995
Richmond, BC · 67,619 km	$29,995
Mississauga, ON · 73,741 km	$34,900
North York, ON · 94,929 km	$29,975

§4 EVENTS

2014	Model year 2014[1] Assembly plant Leipzig, Germany
25 Apr 2019	Transport Canada recall 2019200[2] Issued for the model year · Electrical
12 Jun 2019	Transport Canada recall 2019290[2] Issued for the model year · Powertrain
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
17 Jun 2026	Transport Canada recall 2026301[2] Issued for the model year · Other

21 Oct 2026	Listed for sale, Richmond, BC[5] Newmate Auto Group · asking $29,999
29 Oct 2026	Listing last updated[5] asking $29,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 7 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.