

Register entry, as of 26 October 2026

Listed for sale

Record ID 66aad45b5922

1992 Porsche 911

3.6 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0 AB296 0 N S 420435

WMI 1-3

Dr. Ing. H.C.F. Porsche Ag

DESCRIPTOR 4-8

911 · 3.6 L

CHECK 9

Computes

YEAR 10

1992

PLANT 11

Stuttgart

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	1992	Engine	3.6 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	Not in the decode	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Coupe	Plant	Stuttgart, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/1992

4 recalls listed by Transport Canada for this model year

Steering

1996120 2 Aug 1996

A PART OF THE STEERING COLUMN UPPER UNIVERSAL JOINT MAY HAVE DEVELOPED CRACKS DURING THE MANUFACTURING PROCESS. IF EXPOSED TO HIGH FORCES, SUCH AS FROM SINGLE SIDE CURB CONTACT, THE DEFECTIVE PART OF THE UNIVERSAL JOINT MAY DEVELOP EXCESSIVE TOLERANCES. THIS MAY RESULT IN NOISE AND FREE PLAY IN THE STEERING SYSTEM. IF UNCORRECTED, THE PART MAY FURTHER DETERIORATE AND EVENTUALLY RESULT IN LOSS OF STEERING CONTROL. CORRECTION: UNIVERSAL JOINT WILL BE INSPECTED FOR CRACKS AND REPLACED IF NECESSARY.

Brakes

1994005 13 Jan 1994

UNFAVORABLE TOLERANCES IN THE HYDRAULIC BRAKE PRESSURE REDUCTION VALVE MAY LEAD TO REAR WHEEL LOCK-UP. THIS COULD RESULT IN A POSSIBLE CRASH. CORRECTION: A MODIFIED HYDRAULIC BRAKE PRESSURE VALVE WILL BE INSTALLED ON AFFECTED VEHICLES.

Electrical

1994004 13 Jan 1994

THE REAR HEATER BLOWER RESISTOR CAN BECOME ELECTRICALLY OVERLOADED DUE TO A BINDING OR SEIZED REAR HEATER BLOWER. THE OVERLOADED RESISTOR CAN CREATE SUFFICIENT HEAT TO IGNITE THE PLASTIC AIR PIPE TO WHICH IT IS CONNECTED AND AN ENGINE COMPARTMENT FIRE COULD OCCUR. CORRECTION: A NEW RESISTOR WITH A CIRCUIT BREAKER WILL BE INSTALLED ON AFFECTED VEHICLES.



Engine

1992126 5 Oct 1992


ON VEHICLES WITH CRUISE CONTROL, THE PLASTIC BALL SOCKET ON THE CRUISE CONTROL LINKAGE CAN BREAK. IF THIS SHOULD OCCUR, THE CRUISE CONTROL LINKAGE MIGHT BECOME DETACHED ON ONE END AND COULD JAM ON NEARBY COMPONENTS. THIS COULD IMPAIR THE THROTTLE PLATE OPERATION AND PREVENT THE ENGINE FROM RETURNING TO IDLE WHICH COULD RESULT IN LOSS OF VEHICLE CONTROL. CORRECTION: NEW CRUISE CONTROL LINKAGE WITH STEEL BALL SOCKETS WILL BE INSTALLED ON AFFECTED VEHICLES. IN ADDITION, THE CRUISE CONTROL RELAY LEVER WILL BE LUBRICATED.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.
No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$258,888^[5], the median^[4].



Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

1992 Model year 1992^[1]
Assembly plant Stuttgart, Germany

5 Oct 1992 Transport Canada recall 1992126^[2]
Issued for the model year · Engine

13 Jan 1994 Transport Canada recall 1994005^[2]
Issued for the model year · Brakes

13 Jan 1994 Transport Canada recall 1994004^[2]
Issued for the model year · Electrical

2 Aug 1996 Transport Canada recall 1996120^[2]
Issued for the model year · Steering

25 Sep 2026 Listed for sale, Calgary, AB^[5]
Pfaff Reserve Calgary · asking \$258,888

26 Oct 2026 Listing last updated^[5]
asking \$258,888



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

