

Register entry, as of 29 October 2026

Listed for sale

Record ID 6af7b6ba8ce0

2014 Porsche Cayman S

3.4 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0

AB2A8

5

E

K

190890

WMI 1-3

Dr. Ing. H.C.F. Porsche Ag

DESCRIPTOR 4-8

Cayman · 3.4 L

CHECK 9

Computes

YEAR 10

2014

PLANT 11

Osnabruek

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.4 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Cayman	Drive	Not in the decode
Trim	S	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Coupe	Plant	Osnabruek, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/cayman/2014

5 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Suspension

2021539 1 Sep 2021

Issue: On certain vehicles, the rear axle carrier side mounts may crack and eventually break. If both mounts break while driving, there could be a sudden loss of vehicle control. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear axle carrier side sections.

Other

2019621 11 Dec 2019

Issue: On certain cars, the owner's manual may be missing instructions on how to properly install a child seat. Safety Risk: If a user does not understand how to properly install a child seat, there could be an increased risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your car to a dealer to receive a supplementary owner's manual booklet with the missing information.



Structure

2014498 3 Nov 2014

On certain vehicles the front hood lock may have been improperly manufactured. The front hood lock upper components, on which the catch bar are riveted to the mounting plate, were not produced according to specifications. This could result in the hood opening unexpectedly while the vehicle is being driven. This could compromise the driver's ability to see the road and its users, as well as cause damage to the windshield, which could result in a crash causing injury and/or property damage. Correction: Dealers will replace the upper part of the lock on the front hood.

Airbag

2013351 9 Oct 2013


On certain vehicles, a defective wiring harness in the passenger seat may result in the deactivation of the passenger side frontal and knee airbags, illuminating the airbag warning lamp. Failure of the passenger airbags to deploy during a crash (where deployment is warranted) could increase the risk of injury to the seat occupant. Correction: Dealers will replace the passenger seat in affected vehicles.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.
No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$79,900^[5], the median^[4].



Same model year · 1 live listings · as of 29 Oct 2026

§4 EVENTS

2014	Model year 2014 ^[1] Assembly plant Osnabruek, Germany
9 Oct 2013	Transport Canada recall 2013351 ^[2] Issued for the model year · Airbag
3 Nov 2014	Transport Canada recall 2014498 ^[2] Issued for the model year · Structure
11 Dec 2019	Transport Canada recall 2019621 ^[2] Issued for the model year · Other
1 Sep 2021	Transport Canada recall 2021539 ^[2] Issued for the model year · Suspension
31 Aug 2022	Transport Canada recall 2022487 ^[2] Issued for the model year · Lights and instruments
28 Oct 2026	Listed for sale, Toronto, ON ^[5] World Fine Cars · asking \$79,900



29 Oct 2026 Listing last updated^[5]
asking \$79,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

