Register entry, as of 27 October 2026 Listed for sale Record ID 07fe6ece9371

# 2023 Porsche 911 Carrera S / 4S / GTS / 4 GTS

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WP0 | AB2A9 | 7 | P | S | 221522 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dr. Ing. H.C.F. Porsche Ag | 911 · 3.0 L | Computes | 2023 | Stuttgart | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.0 L, 6 cylinders |
| Make | Porsche | Fuel | Gasoline |
| Model | 911 | Drive | Not in the decode |
| Trim | Carrera S / 4S / GTS / 4 GTS | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Coupe | Plant | Stuttgart, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2023

**6** recalls listed by Transport Canada for this model year

### Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

### Seats and restraints

2025067 12 Feb 2025

Issue: On certain vehicles, the bolts that attach the rear passenger seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the rear seat belt buckle attachment bolts. The dealer will also reposition the noise-reducing mat, as necessary.

### Structure

2024128 27 Feb 2024

Issue: On certain vehicles, the windshield and/or the rear window may not be properly attached. As a result, the front airbag(s) may not inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield and/or rear window.

### Seats and restraints

2024107 20 Feb 2024

Issue: On certain vehicles, the rear passenger seat belts may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rear seat belt(s).

### Airbag

2023571 25 Oct 2023

Issue: On certain vehicles equipped with optional full bucket seats, the seat-mounted airbags could deploy in a crash that doesn't require them to. Safety Risk: A seat-mounted airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the airbag control unit software.

### Lights and instruments

2023362 28 Jun 2023

Issue: On certain 911 GT3 Touring models, when the rear spoiler is raised manually, both the main and auxiliary center high-mounted stop lamps may switch on when the vehicle is braking. Canadian regulations only allow one of the two centre high-mounted stop lamps to be switched on while braking. Safety Risk: Multiple stop lamps that turn on at the same time could cause confusion for other drivers and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to reprogram the rear spoiler control unit.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $222,900[5], the median[4].

| | |
|---|---|
| Lowest ask | $169,790 |
| Middle half | $202,248 – $329,388 |
| Median ask | $222,900 |
| This car | $222,900 |

Same model year · 19 live listings · as of 27 Oct 2026

### OTHER 2023 PORSCHE 911 LISTINGS [5]

| | |
|---|---|
| Chilliwack, BC · 42,372 km | $189,995 |
| Vaughan, ON · 26,271 km | $225,000 |
| Oakville, ON · 25,682 km | $169,790 |
| Calgary, AB · 8,100 km | $328,888 |
| Toronto, ON · 22,780 km | $199,495 |
| Aurora, ON · 22,780 km | $199,495 |

## §4 EVENTS

2023 **Model year 2023**[1]
Assembly plant Stuttgart, Germany

| | |
|---|---|
| 28 Jun 2023 | Transport Canada recall 2023362[2]<br>Issued for the model year · Lights and instruments |
| 25 Oct 2023 | Transport Canada recall 2023571[2]<br>Issued for the model year · Airbag |
| 20 Feb 2024 | Transport Canada recall 2024107[2]<br>Issued for the model year · Seats and restraints |
| 27 Feb 2024 | Transport Canada recall 2024128[2]<br>Issued for the model year · Structure |
| 12 Feb 2025 | Transport Canada recall 2025067[2]<br>Issued for the model year · Seats and restraints |
| 19 Dec 2025 | Transport Canada recall 2025716[2]<br>Issued for the model year · Visual system |
| 25 Oct 2026 | Listed for sale, Kirkland, QC[5]<br>John Scotti Luxury Prestige · asking $222,900 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $222,900 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 19 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.