Register entry, as of 6 November 2026 Listed for sale Record ID da89db15f49c

2024 Porsche 911 Carrera S, Carrera 4S, Carrera GTS, Carrera 4 GTS, Dakar

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	AB2A9	7	R	S	221779
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	911 · 3.0 L	Computes	2024	Stuttgart	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	Carrera S, Carrera 4S, Carrera GTS, Carrera 4 GTS, Dakar	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Coupe	Plant	Stuttgart, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2024

5 recalls listed by Transport Canada for this model year

Wheels

2026502 16 Oct 2026

Issue: On certain vehicles, the center wheel lock(s) may not have been manufactured properly. As a result, the wheel lock(s) could break and cause the wheel(s) to separate from the vehicle. Note: This recall is an expansion of Transport Canada recall no. 2024-646. This recall only affects certain vehicles equipped with optional central locking wheels. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a hazard for others. Corrective Actions: To reduce the safety risk, Porsche advises not to drive your vehicle until the recall repairs are completed. Porsche will notify owners by mail and advise you to contact a dealer to arrange to have the vehicle towed to the dealership. The dealer will inspect and, if necessary, replace the center wheel lock(s).

Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

Wheels

2024646 28 Oct 2024

Issue: On certain vehicles, the center wheel lock(s) may not have been manufactured properly. As a result, the wheel lock(s) could break and cause the wheel(s) to separate from the vehicle. Note: This recall only affects certain vehicles equipped with optional central locking wheels. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a hazard for others. Corrective Actions: To reduce the safety risk, Porsche advises not to drive your vehicle until the recall repairs are completed. Porsche will notify owners by mail and advise you to contact a dealer to arrange to have the vehicle towed to the dealership. The dealer will inspect and, if necessary, replace the center wheel lock(s).

Structure

2024128 27 Feb 2024

Issue: On certain vehicles, the windshield and/or the rear window may not be properly attached. As a result, the front airbag(s) may not inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield and/or rear window.

Airbag

2023571 25 Oct 2023


Issue: On certain vehicles equipped with optional full bucket seats, the seat-mounted airbags could deploy in a crash that doesn't require them to. Safety Risk: A seat-mounted airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the airbag control unit software.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.
No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $218,888[5], $25,556 under the median of $244,444[4].



Lowest ask	$166,888
Middle half	$214,396 – $294,141
Median ask	$244,444
This car	$218,888

Same model year · 22 live listings · as of 6 Nov 2026

OTHER 2024 PORSCHE 911 LISTINGS [5]

Langley, BC · 10,800 km	$196,888
Vancouver, BC · 7,700 km	$166,888
Vancouver, BC · 10,800 km	$198,888
North Bay, ON · 1,803 km	$328,888
Montréal, QC · 7,647 km	$298,888

§4 EVENTS

2024	Model year 2024[1] Assembly plant Stuttgart, Germany
25 Oct 2023	Transport Canada recall 2023571[2] Issued for the model year · Airbag

27 Feb 2024	Transport Canada recall 2024128[2] Issued for the model year · Structure
28 Oct 2024	Transport Canada recall 2024646[2] Issued for the model year · Wheels
19 Dec 2025	Transport Canada recall 2025716[2] Issued for the model year · Visual system
16 Oct 2026	Transport Canada recall 2026502[2] Issued for the model year · Wheels
4 Nov 2026	Listed for sale, Vancouver, BC[5] MINI Vancouver · asking $218,888
6 Nov 2026	Listing last updated[5] asking $218,888

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 22 live listings, as of 6 Nov 2026

[5] Live public dealer listings on Cardog, as of 6 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.