Register entry, as of 28 October 2026 Listed for sale Record ID b249388f8635

2022 Porsche 911 Carrera S / 4S / GTS / 4 GTS

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
WP0	AB2A9	8	N	S	221607
Dr. Ing. H.C.F. Porsche Ag	911 · 3.0 L	Computes	2022	Stuttgart	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	Carrera S / 4S / GTS / 4 GTS	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Coupe	Plant	Stuttgart, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2022

4 recalls listed by Transport Canada for this model year

Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

Structure

2024128 27 Feb 2024

Issue: On certain vehicles, the windshield and/or the rear window may not be properly attached. As a result, the front airbag(s) may not inflate properly in a crash. Safety Risk: An airbag that doesn't inflate properly could create an increased risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield and/or rear window.

Airbag

2023571 25 Oct 2023

Issue: On certain vehicles equipped with optional full bucket seats, the seat-mounted airbags could deploy in a crash that doesn't require them to. Safety Risk: A seat-mounted airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the airbag control unit software.

Lights and instruments

2023362 28 Jun 2023

Issue: On certain 911 GT3 Touring models, when the rear spoiler is raised manually, both the main and auxiliary center high-mounted stop lamps may switch on when the vehicle is braking. Canadian regulations only allow one of the two centre high-mounted stop lamps to be switched on while braking. Safety Risk: Multiple stop lamps that turn on at the same time could cause confusion for other drivers and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to reprogram the rear spoiler control unit.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $192,900[5], $12,920 over the median of $179,980[4].



Lowest ask	$164,988
Middle half	$169,000 – $192,900
Median ask	$179,980
This car	$192,900

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2022 PORSCHE 911 LISTINGS [5]

Victoria, BC · 20,102 km	$168,900
Montréal, QC · 36,770 km	$299,900
Montréal, QC · 22,044 km	$189,888
Calgary, AB · 20,994 km	$219,888
Calgary, AB · 6,052 km	$318,888
Concord, ON · 38,348 km	$177,800

§4 EVENTS

2022	Model year 2022[1] Assembly plant Stuttgart, Germany
28 Jun 2023	Transport Canada recall 2023362[2] Issued for the model year · Lights and instruments
25 Oct 2023	Transport Canada recall 2023571[2] Issued for the model year · Airbag
27 Feb 2024	Transport Canada recall 2024128[2] Issued for the model year · Structure
19 Dec 2025	Transport Canada recall 2025716[2] Issued for the model year · Visual system

25 Oct 2026	Listed for sale, Kirkland, QC[5] John Scotti Luxury Prestige · asking $192,900
27 Oct 2026	Listing last updated[5] asking $192,900

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.