

Register entry, as of 28 October 2026

Listed for sale

Record ID 6232c458c0b4

2016 Porsche Panamera S E-Hybrid

3.0 L, 6 cylinders · Sedan · Electric

VEHICLE IDENTIFICATION NUMBER [1]

WP0 AD2A7 X G L 040823

WMI 1-3

Dr. Ing. H.C.F. Porsche Ag

DESCRIPTOR 4-8

Panamera · 3.0 L

CHECK 9

Computes

YEAR 10

2016

PLANT 11

Leipzig

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Electric
Model	Panamera	Drive	Not in the decode
Trim	S E-Hybrid	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sedan	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/panamera/2016

5 recalls listed by Transport Canada for this model year

Other 2026301 17 Jun 2026

Issue: On certain vehicles, the immobilizer system may not meet certain requirements of Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Porsche has made changes to ensure that all new vehicles meet Canadian regulations.

Lights and instruments 2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Airbag 2019353 18 Jul 2019

Issue: On certain vehicles, the airbag electronic control unit could be damaged by an electrical fault. This could cause the airbag system not to work properly in a crash. It could also result in a deployment of the airbags and/or seat belt pretensioners without a crash. Safety Risk: Airbags that do not work properly in a crash could create an increased risk of injury. Airbags or seat belt pretensioners that deploy without a crash could create a risk of injury and also increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the airbag control module. If an electrical fault is detected, the airbag control module will be replaced.



Powertrain

2019290 12 Jun 2019

Issue: On certain vehicles, the transmission shifter could detach from the transmission. This could cause the transmission not to shift gears when the shifter is moved. As a result, the transmission could be in a different gear than the gear shifter indicates. If a driver attempts to exit the vehicle while the transmission is not in Park, and the parking brake is not applied, the vehicle could move suddenly. Safety Risk: Sudden and unexpected movement of the vehicle could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct them to take their vehicle to a dealer to replace the shifter cable bushing. Owners are reminded to use the parking brake anytime the vehicle is parked.

Electrical

2019200 25 Apr 2019

Issue: On certain cars, water could leak into the air conditioning blower control unit. Over time, this could cause a short circuit that could cause it to melt or burn. This could happen while driving or after the vehicle is parked and shut off. Safety Risk: A short circuit in the blower control unit could create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and advise them what to do. When a remedy is available, owners will be requested to bring their car to a dealership for repair. Owners are advised to park their car outdoors until the recall repairs have been completed.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.

No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$39,990^[5], the median^[4].



Lowest ask	\$27,772
Middle half	\$34,888 – \$39,995
Median ask	\$39,990
This car	\$39,990

Same model year · 5 live listings · as of 28 Oct 2026

OTHER 2016 PORSCHE PANAMERA LISTINGS ^[5]

Woodbridge, ON · 106,000 km	\$45,988
Richmond, BC · 82,642 km	\$39,995
North York, ON · 102,000 km	\$34,888
Mississauga, ON · 113,100 km	\$27,772

§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Leipzig, Germany
25 Apr 2019	Transport Canada recall 2019200 ^[2] Issued for the model year · Electrical
12 Jun 2019	Transport Canada recall 2019290 ^[2] Issued for the model year · Powertrain
18 Jul 2019	Transport Canada recall 2019353 ^[2] Issued for the model year · Airbag



31 Aug 2022	Transport Canada recall 2022487 ^[2] Issued for the model year · Lights and instruments
17 Jun 2026	Transport Canada recall 2026301 ^[2] Issued for the model year · Other
24 Oct 2026	Listed for sale, New Westminster, BC ^[5] Inline Motors · asking \$39,990
28 Oct 2026	Listing last updated ^[5] asking \$39,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

