Register entry, as of 29 October 2026 Listed for sale Record ID 1084a2d741c3

2024 Porsche Taycan GTS

AWD · Sedan · Electric

VEHICLE IDENTIFICATION NUMBER [1]

WP0	AD2Y1	2	R	S	A47231
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Taycan	Computes	2024	Stuttgart	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	Not in the decode
Make	Porsche	Fuel	Electric
Model	Taycan	Drive	AWD
Trim	GTS	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sedan	Plant	Stuttgart, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/taycan/2024

7 recalls listed by Transport Canada for this model year

Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

Heater and defroster

2025572 20 Oct 2025

Issue: On certain vehicles, the recall repairs completed by a Porsche dealer during recall APA7 (Transport Canada recall no. 2023-313) may not be effective. As a result, a second repair may be required. On certain vehicles, the high-voltage electric heater could fail. If this happens, you may experience reduced cabin heat, and the windshield defrost system may not work properly. Note: This recall replaces Transport Canada recall no. 2023-313. Safety Risk: A windshield defroster that doesn't work may cause reduced visibility and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail. For certain vehicles, as an interim repair, Porsche will advise you to take your vehicle to a dealership to replace the passenger compartment high-voltage electric heater with a new part of the same design. When the final repairs are available, Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger compartment high-voltage electric heater with an improved part.

High voltage

2024582 2 Oct 2024

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall is an expansion of Transport Canada recall nos. 2023-661, 2024-180 and 2024-181. Certain vehicles that were repaired under these recalls also require this repair. Safety Risk: A short circuit in the high-voltage battery can create a fire risk. Corrective Actions: To reduce the safety risk, Porsche recommends that you set the maximum charge setting of your vehicle at 80% until the recall repairs are completed. Porsche will notify owners by mail. As an interim repair, a dealer will inspect and, if necessary, replace the high-voltage battery modules. Once the final repair is available, Porsche will notify you by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem.

Brakes

2024353 19 Jun 2024

Issue: On certain vehicles, the front brake hoses could fail and cause a progressive brake fluid leak. If this happens, you may experience a change in brake pedal feel and travel. This can cause reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the front brake hoses.

Lights and instruments

2024339 14 Jun 2024

Issue: On certain vehicles, a software problem could cause the headlamps to become incorrectly aimed while reversing. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps that aren't aimed correctly could cause reduced visibility and/or glare for oncoming drivers and could increase the risk of a crash. Corrective Action: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the central control unit software.

High voltage

2024181 20 Mar 2024

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall is an expansion of Transport Canada recall number 2023-661. Safety Risk: A short circuit in the high-voltage battery can create a fire risk. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery modules. To reduce the safety risk, Porsche recommends that you set the maximum charge setting of your vehicle at 80% until the recall repairs are completed.

1 more on the model-year record, cardog.app/tools/recalls/porsche/taycan/2024

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $120,995[5], the median[4].

Lowest ask	$89,995
Middle half	$104,995 – $138,888
Median ask	$120,995
This car	$120,995

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2024 PORSCHE TAYCAN LISTINGS [5]

Toronto, ON · 85,741 km	$89,995
Mississauga, ON · 315 km	$138,888
Richmond, BC · 1,620 km	$145,995

§4 EVENTS

2024	Model year 2024[1] Assembly plant Stuttgart, Germany
13 Dec 2023	Transport Canada recall 2023662[2] Issued for the model year · Accessories
20 Mar 2024	Transport Canada recall 2024181[2] Issued for the model year · High voltage
14 Jun 2024	Transport Canada recall 2024339[2] Issued for the model year · Lights and instruments
19 Jun 2024	Transport Canada recall 2024353[2] Issued for the model year · Brakes
2 Oct 2024	Transport Canada recall 2024582[2] Issued for the model year · High voltage
20 Oct 2025	Transport Canada recall 2025572[2] Issued for the model year · Heater and defroster
19 Dec 2025	Transport Canada recall 2025716[2] Issued for the model year · Visual system
27 Oct 2026	Listed for sale, Toronto, ON[5] Porsche Centre Downtown Toronto · asking $120,995
29 Oct 2026	Listing last updated[5] asking $120,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.