Register entry, as of 26 October 2026 Listed for sale Record ID 67ba44b89ff2

2012 Porsche 911 Cabriolet (2WD), 4 Cabriolet (4WD)

3.6 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	CA2A9	6	C	S	140629
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	911 · 3.6 L	Computes	2012	Stuttgart-Zuffenhausen	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	3.6 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	Cabriolet (2WD), 4 Cabriolet (4WD)	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Convertible	Plant	Stuttgart-Zuffenhausen, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2012

3 recalls listed by Transport Canada for this model year

Other

2013061 22 Feb 2013

On certain vehicles, exhaust tailpipes can fracture and detach from mufflers. A tailpipe separating from the vehicle could strike another vehicle, a stationary object, or a bystander, causing property damage and/or personal injury. Correction: Dealers will replace both muffler assemblies.

Fuel system

2012102 20 Mar 2012

On certain vehicles, a fuel line quick connector could uncouple as a result of contact with a coolant pipe. Fuel leakage, in the presence of an ignition source, could result in a fire. Fuel leakage could also cause the engine to misfire and stall. Engine stalling would result in lost vehicle propulsion which, in conjunction with traffic and road condition, and the driver's reactions, could increase the risk of a crash. These issues could result in property damage and/or personal injury. Correction: Dealers will install a spacer ring to prevent contact between the fuel line quick connector and the coolant pipe.

Seats and restraints

2011293 12 Aug 2011

On certain vehicles, the seatbelt anchors were manufactured incorrectly and, as a result, may not rotate as designed. Failure of the seatbelt anchorage to restrain the occupant as intended would increase the risk of personal injury during a crash. Correction: Dealers will inspect and, if necessary, replace the seatbelt anchors.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.
No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $102,888[5], $19,283 over the median of $83,605[4].

Lowest ask	$69,995
Middle half	$76,800 – $93,246
Median ask	$83,605
This car	$102,888

Same model year · 3 live listings · as of 26 Oct 2026

OTHER 2012 PORSCHE 911 LISTINGS [5]

Granby, QC · 116,788 km	$69,995
Calgary, AB · 45,947 km	$83,605

§4 EVENTS

2012	Model year 2012[1] Assembly plant Stuttgart-Zuffenhausen, Germany
12 Aug 2011	Transport Canada recall 2011293[2] Issued for the model year · Seats and restraints
20 Mar 2012	Transport Canada recall 2012102[2] Issued for the model year · Fuel system
22 Feb 2013	Transport Canada recall 2013061[2] Issued for the model year · Other
14 Oct 2026	Listed for sale, Montréal, QC[5] Rolls-Royce Motor Cars Quebec · asking $102,888
26 Oct 2026	Listing last updated[5] asking $102,888

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.