Register entry, as of 26 October 2026 Listed for sale Record ID 6214cbcd6334

2017 Porsche 911 S, GTS, 4S, 4 GTS

3.8 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	CB2A9	3	H	S	154945
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	911 · 3.8 L	Computes	2017	Stuttgart-Zuffenhausen	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.8 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	S, GTS, 4S, 4 GTS	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Convertible	Plant	Stuttgart-Zuffenhausen, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2017

5 recalls listed by Transport Canada for this model year

Airbag

2019353 18 Jul 2019

Issue: On certain vehicles, the airbag electronic control unit could be damaged by an electrical fault. This could cause the airbag system not to work properly in a crash. It could also result in a deployment of the airbags and/or seat belt pretensioners without a crash. Safety Risk: Airbags that do not work properly in a crash could create an increased risk of injury. Airbags or seat belt pretensioners that deploy without a crash could create a risk of injury and also increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the airbag control module. If an electrical fault is detected, the airbag control module will be replaced.

Structure

2017110 2 Mar 2017

On certain vehicles, the windshield may not have been properly bonded to the car body. This could allow the glass panel to separate from the vehicle in the event of a crash which would increase the risk of injury to the occupants. Correction: Dealers will re-bond the windshield to the car body.

Airbag

2017109 2 Mar 2017

Certain vehicles may have been equipped with a front passenger airbag that does not meet specifications. This could cause the front passenger airbag to fail to deploy properly in the event of a crash that warrants deployment of the passenger frontal airbag, which could increase the risk of injury to the occupants. Correction: Dealers will replace front passenger airbag module.

Fuel system

2017041 25 Jan 2017

On certain vehicles and replacement engines, the fastening screws for the fuel collection pipes could shear off due to stress corrosion cracking. If this occurs, fuel could leak into the engine compartment which, in the presence of an ignition source, could result in a fire causing injury and/or damage to property. Correction: Dealers will replace the fastening screws of each of the collection pipes with new and improved screws.

Airbag

2016654 22 Dec 2016

Certain vehicles may have been equipped with side airbag inflators (located in the front seat backrests) that do not meet specifications. This could cause affected airbags to fail to deploy properly in the event of a lateral crash, which could increase the risk of injury to the occupants. Correction: Dealers will replace affected airbag modules.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $118,900[5], $17,950 under the median of $136,850[4].

Lowest ask	$114,900
Middle half	$121,971 – $177,116
Median ask	$136,850
This car	$118,900

Same model year · 8 live listings · as of 26 Oct 2026

OTHER 2017 PORSCHE 911 LISTINGS [5]

Concord, ON · 66,874 km	$123,800
Montréal, QC · 30,391 km	$149,900
Mont-Royal, QC · 30,391 km	$149,900
Woodbridge, ON · 65,000 km	$169,988
Kelowna, BC · 36,650 km	$144,990
Mont-royal, QC · 59,000 km	$198,500

§4 EVENTS

2017	Model year 2017[1] Assembly plant Stuttgart-Zuffenhausen, Germany
22 Dec 2016	Transport Canada recall 2016654[2] Issued for the model year · Airbag
25 Jan 2017	Transport Canada recall 2017041[2] Issued for the model year · Fuel system
2 Mar 2017	Transport Canada recall 2017110[2] Issued for the model year · Structure
2 Mar 2017	Transport Canada recall 2017109[2] Issued for the model year · Airbag
18 Jul 2019	Transport Canada recall 2019353[2] Issued for the model year · Airbag

26 Oct 2026 **Listed for sale, Mont-Royal, QC**[5]
Claireview Leasing · asking $118,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.