Register entry, as of 27 October 2026 Listed for sale Record ID b7b27e0f120f

2020 Porsche 911 Carrera S Cabriolet / Carrera 4S Cabriolet

3.0 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP0	CB2A9	5	L	S	262198
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	911 · 3.0 L	Computes	2020	Stuttgart	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	911	Drive	Not in the decode
Trim	Carrera S Cabriolet / Carrera 4S Cabriolet	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Convertible	Plant	Stuttgart, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/911/2020

5 recalls listed by Transport Canada for this model year

Other

2026301 17 Jun 2026

Issue: On certain vehicles, the immobilizer system may not meet certain requirements of Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Porsche has made changes to ensure that all new vehicles meet Canadian regulations.

Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

Seats and restraints

2023145 17 Mar 2023

Issue: On certain vehicles, the seat belt reminder chime may not sound to alert you that the front passenger seat belt isn't buckled. Canadian regulations require both a seat belt reminder sound and visual tell-tale when you switch the vehicle on, and the passenger isn't wearing their seat belt. Safety Risk: A seat belt warning that doesn't work correctly may not remind you to ensure that your passenger is buckled. Not wearing a seat belt can increase the risk of injury in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to reprogram the instrument cluster software.

Lights and instruments

2019622 11 Dec 2019

Issue: On certain cars, the hazard warning lights may not turn on when they are switched on. Specifically, if a driver is in the car with the seat belt unbuckled and the ignition off, after 90 seconds, if an attempt is made to turn on the hazard lights, they may not turn on. Safety Risk: Hazard lights that do not turn on could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your car to a dealer to update the control unit software.

Powertrain

2019291 12 Jun 2019

Issue: On certain vehicles, the nut that connects the driveshaft to the wheel hub may not be tightened correctly. Over time, the nut could loosen and may result in the driveshaft disconnecting. This could cause a loss of power to the drive wheels. Additionally, if the parking brake is not applied, this could allow the car to roll away. Safety Risk: A loss of power to the drive wheels or sudden, unexpected movement of the car could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct them to take their vehicle to a dealer to replace the nut with a new one and ensure it is tightened correctly.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $139,995[5], $17,000 under the median of $156,995[4].



Lowest ask	$139,995
Middle half	$149,900 – $159,888
Median ask	$156,995
This car	$139,995

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2020 PORSCHE 911 LISTINGS [5]

St-Eustache, QC · 32,230 km	$159,888
Vancouver, BC · 9,300 km	$173,000
Vaughan, ON · 64,157 km	$149,900
Vaughan, ON · 47,663 km	$157,900
Aurora, ON · 28,509 km	$159,999
Richmond, BC · 43,562 km	$143,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Stuttgart, Germany
12 Jun 2019	Transport Canada recall 2019291[2] Issued for the model year · Powertrain
11 Dec 2019	Transport Canada recall 2019622[2] Issued for the model year · Lights and instruments

17 Mar 2023	Transport Canada recall 2023145[2] Issued for the model year · Seats and restraints
19 Dec 2025	Transport Canada recall 2025716[2] Issued for the model year · Visual system
17 Jun 2026	Transport Canada recall 2026301[2] Issued for the model year · Other
6 Oct 2026	Listed for sale, Richmond, BC[5] Transparent Motorcars · asking $139,995
27 Oct 2026	Listing last updated[5] asking $139,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.