Register entry, as of 28 October 2026 Listed for sale Record ID cf0254a4f51b

# 2021 Porsche Macan Base

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WP1 | AA2A5 | 2 | M | L | B07870 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dr. Ing. H.C.F. Porsche Ag | Macan · 2.0 L | Computes | 2021 | Leipzig | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Porsche | Fuel | Gasoline |
| Model | Macan | Drive | AWD |
| Trim | Base | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Sport Utility Vehicle | Plant | Leipzig, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2021

**2** recalls listed by Transport Canada for this model year

### Seats and restraints

2023361 27 Jun 2023

Issue: On a small number of vehicles, the rear outboard seat belt anchor bolts may not have been properly tightened. As a result, the rear outboard seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and right rear seat belt anchor bolts.

### Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $39,980[5], $9,007 under the median of $48,987[4].

| | |
|---|---|
| Lowest ask | $37,995 |
| Middle half | $41,995 – $55,999 |
| Median ask | $48,987 |
| This car | $39,980 |

Same model year · 29 live listings · as of 28 Oct 2026

### OTHER 2021 PORSCHE MACAN LISTINGS [5]

| | |
|---|---|
| Brampton, ON · 72,437 km | $46,920 |
| Anjou, QC · 30,000 km | $43,500 |
| Mississauga, ON · 105,801 km | $38,999 |
| St-Eustache, QC · 97,695 km | $48,897 |
| Westbank, BC · 87,889 km | $46,999 |
| Dollard-des-Ormeaux, QC · 76,761 km | $43,524 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Leipzig, Germany |
| 31 Aug 2022 | Transport Canada recall 2022487[2]<br>Issued for the model year · Lights and instruments |
| 27 Jun 2023 | Transport Canada recall 2023361[2]<br>Issued for the model year · Seats and restraints |
| 29 Jul 2026 | Listed for sale, Burnaby, BC[5]<br>Morrey Volvo Cars Of Burnaby · asking $39,980 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $39,980 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 29 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.