Register entry, as of 26 November 2026 Listed for sale Record ID d799381202c7

# 2024 Porsche Cayenne Cayenne

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WP1 | AA2AY | 6 | R | D | A06942 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dr. Ing. H.C.F. Porsche Ag | Cayenne · 3.0 L | Computes | 2024 | Bratislava | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 3.0 L, 6 cylinders |
| Make | Porsche | Fuel | Gasoline |
| Model | Cayenne | Drive | AWD |
| Trim | Cayenne | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Sport Utility Vehicle | Plant | Bratislava, Slovakia |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/cayenne/2024

**7** recalls listed by Transport Canada for this model year

### Visual system

2025716 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the driver assistance system control unit software.

### Fuel system

2025498 23 Sep 2025

Issue: On certain vehicles, the connections on the high-pressure fuel pumps may not have been tightened properly. As a result, the fuel could leak. Note: This recall only affects certain vehicles equipped with a V8 engine. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to inspect the connections on the high-pressure fuel pumps. The high-pressure fuel pump(s) and fuel line(s) will be replaced, as necessary.

### Suspension

2024408 17 Jul 2024

Issue: On certain vehicles, the left-front upper control arm may not have been manufactured correctly. As a result, the control arm could break and cause a sudden loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the left-front upper control arm.

### Lights and instruments

2024384 2 Jul 2024

Issue: On certain vehicles, a software problem could cause the front turn signals to be the wrong colour when the vehicle is parked and the hazard lights are turned on. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Hazard lights that are the wrong colour could create confusion for others and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the headlight control unit software.

### Lights and instruments

2024339 14 Jun 2024

Issue: On certain vehicles, a software problem could cause the headlamps to become incorrectly aimed while reversing. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps that aren't aimed correctly could cause reduced visibility and/or glare for oncoming drivers and could increase the risk of a crash. Corrective Action: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the central control unit software.

### Accessories

2023662 13 Dec 2023

Issue: Under certain conditions, the 220 V vehicle charging cable plug could become damaged by the house power outlet. As a result, the charging cable could overheat while charging. Note: This recall only affects electric and plug-in hybrid electric (PHEV) models. Safety Risk: A charging cable that overheats could create a fire risk. Corrective Actions: Porsche will notify owners by mail and advise you to take your 220 V vehicle charger to a dealership to replace the vehicle charging cable.

1 more on the model-year record, cardog.app/tools/recalls/porsche/cayenne/2024

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $84,996[5], $2,009 over the median of $82,987[4].




| | |
|---|---|
| Lowest ask | $73,900 |
| Middle half | $77,998 – $86,888 |
| Median ask | $82,987 |
| This car | $84,996 |

Same configuration · 9 live listings · as of 26 Nov 2026

### OTHER 2024 PORSCHE CAYENNE LISTINGS [5]

| | |
|---|---|
| Montréal, QC · 27,998 km | $212,980 |
| St-Eustache, QC · 59,986 km | $104,995 |
| Québec, QC · 39,164 km | $214,997 |
| Richmond, BC · 21,500 km | $115,995 |
| Vaughan, ON · 33,948 km | $79,900 |
| Calgary, AB · 38,585 km | $98,980 |

## §4 EVENTS

2024 Model year 2024[1]
Assembly plant Bratislava, Slovakia

| | |
|---|---|
| 31 Jul 2023 | Transport Canada recall 2023419[2]<br>Issued for the model year · Lights and instruments |
| 13 Dec 2023 | Transport Canada recall 2023662[2]<br>Issued for the model year · Accessories |
| 14 Jun 2024 | Transport Canada recall 2024339[2]<br>Issued for the model year · Lights and instruments |
| 2 Jul 2024 | Transport Canada recall 2024384[2]<br>Issued for the model year · Lights and instruments |
| 17 Jul 2024 | Transport Canada recall 2024408[2]<br>Issued for the model year · Suspension |
| 23 Sep 2025 | Transport Canada recall 2025498[2]<br>Issued for the model year · Fuel system |
| 19 Dec 2025 | Transport Canada recall 2025716[2]<br>Issued for the model year · Visual system |
| 26 Nov 2026 | Listed for sale, Greenfield Park, QC[5]<br>Mercedes-Benz Rive-Sud · asking $84,996 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 26 Nov 2026
[5] Live public dealer listings on Cardog, as of 26 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.