Register entry, as of 29 October 2026 Listed for sale Record ID b5c0012028bb

2021 Porsche Macan S

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP1	AB2A5	2	M	L	B34192
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Macan · 3.0 L	Computes	2021	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Macan	Drive	AWD
Trim	S	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sport Utility Vehicle	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2021

2 recalls listed by Transport Canada for this model year

Seats and restraints

2023361 27 Jun 2023

Issue: On a small number of vehicles, the rear outboard seat belt anchor bolts may not have been properly tightened. As a result, the rear outboard seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and right rear seat belt anchor bolts.

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $40,988[5], $5,932 under the median of $46,920[4].



Lowest ask	$38,999
Middle half	$41,995 – $53,297
Median ask	$46,920
This car	$40,988

Same configuration · 13 live listings · as of 29 Oct 2026

OTHER 2021 PORSCHE MACAN LISTINGS [5]

Brampton, ON · 72,437 km	$46,920
Anjou, QC · 30,000 km	$43,500
Mississauga, ON · 105,801 km	$38,999
St-Eustache, QC · 97,695 km	$48,897
Westbank, BC · 87,889 km	$46,999
Dollard-des-Ormeaux, QC · 76,761 km	$43,524

§4 EVENTS

2021	Model year 2021[1] Assembly plant Leipzig, Germany
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
27 Jun 2023	Transport Canada recall 2023361[2] Issued for the model year · Seats and restraints
4 Sep 2026	Listed for sale, Saint-Hubert, QC[5] Action Chevrolet Rive Sud · asking $40,988
26 Oct 2026	Listing last updated[5] asking $40,988

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 13 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.