Register entry, as of 28 October 2026 Listed for sale Record ID 677228d48186

2016 Porsche Macan

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP1	AB2A5	4	G	L	B40189
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Macan · 3.0 L	Computes	2016	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Macan	Drive	Not in the decode
Trim	Not in the decode	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sport Utility Vehicle	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2016

7 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Airbag

2021113 4 Mar 2021

Issue: On certain vehicles, the front passenger seat occupant sensor mat could stop working over time. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: The airbag warning light or passenger airbag OFF light will turn on if the sensor mat stops working. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion and occupant sensor mat.

Fuel system

2020054 13 Feb 2020

Issue: Over time, small cracks could develop in the fuel pump outlet. If this happens, there could be a fuel odour or fuel leak under the rear seat area. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump service cover. The fuel filter flanges will be inspected, and replaced if any cracks are found.

Label
2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

Fuel system
2017241 3 May 2017

On certain vehicles, fine hairline cracks could appear after an extended period of use on the filter flange of the fuel pump. A fuel leak in the presence of an ignition source could cause a fire, increase the risk of injury and/or damage to property. Correction: Dealers will inspect and replace the fuel filter flange if cracks are found. If no cracks are found, a film will be affixed to the filter flange to protect it.

Airbag
2017107 1 Mar 2017

On certain vehicles, the front passenger seat occupancy detection mat conductive fabric may fracture over time. As a result, the passenger airbag could deactivate, illuminating the passenger airbag OFF lamp. Failure of the passenger airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the occupant seat occupancy detection mat with a new improved mat.

1 more on the model-year record, cardog.app/tools/recalls/porsche/macan/2016

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,999[5], $1,445 under the median of $21,444[4].



Lowest ask	$17,800
Middle half	$19,496 – $22,592
Median ask	$21,444
This car	$19,999

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2016 PORSCHE MACAN LISTINGS [5]

Brampton, ON · 96,361 km	$22,500
Surrey, BC · 104,000 km	$22,869
Ottawa, ON · 143,211 km	$20,900
Toronto, ON · 0 km	$17,988
Toronto, ON · 0 km	$21,988
Richmond, BC · 72,510 km	$28,500

§4 EVENTS

2016	Model year 2016[1] Assembly plant Leipzig, Germany
29 Oct 2015	Transport Canada recall 2015514[2] Issued for the model year · Fuel system

1 Mar 2017	Transport Canada recall 2017107[2] Issued for the model year · Airbag
3 May 2017	Transport Canada recall 2017241[2] Issued for the model year · Fuel system
18 Apr 2019	Transport Canada recall 2019192[2] Issued for the model year · Label
13 Feb 2020	Transport Canada recall 2020054[2] Issued for the model year · Fuel system
4 Mar 2021	Transport Canada recall 2021113[2] Issued for the model year · Airbag
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
2 Sep 2026	Listed for sale, North Vancouver District, BC[5] Canwest Auto Inc · asking $19,999
28 Oct 2026	Listing last updated[5] asking $19,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.