Register entry, as of 26 October 2026 Listed for sale Record ID 2ec6d8e271e5

2019 Porsche Macan S

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP1	AB2A5	5	K	L	B30652
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Macan · 3.0 L	Computes	2019	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Macan	Drive	AWD
Trim	S	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sport Utility Vehicle	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2019

3 recalls listed by Transport Canada for this model year

Seats and restraints

2023361 27 Jun 2023

Issue: On a small number of vehicles, the rear outboard seat belt anchor bolts may not have been properly tightened. As a result, the rear outboard seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to replace the left and right rear seat belt anchor bolts.

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Label

2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $35,995[5], the median[4].

Lowest ask	$24,890
Middle half	$34,885 – $37,888
Median ask	$35,995
This car	$35,995

Same model year · 9 live listings · as of 26 Oct 2026

OTHER 2019 PORSCHE MACAN LISTINGS [5]

Dollard-Des Ormeaux, QC · 57,000 km	$35,495
Sainte-Rose - Laval, QC · 105,000 km	$34,885
Montréal, QC · 63,589 km	$37,998
Dorval, QC · 131,676 km	$24,890
Laval, QC · 40,060 km	$36,990
North Vancouver, BC · 144,833 km	$28,895

§4 EVENTS

2019	Model year 2019[1] Assembly plant Leipzig, Germany
18 Apr 2019	Transport Canada recall 2019192[2] Issued for the model year · Label
31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
27 Jun 2023	Transport Canada recall 2023361[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Boisbriand, QC[5] autoabsolue.com · asking $35,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.