Register entry, as of 27 October 2026 Listed for sale Record ID 54a3a7e7ef22

# 2024 Porsche Macan Turbo Electric

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| WP1 | AC2XA | 6 | R | L | 200720 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dr. Ing. H.C.F. Porsche Ag | Macan | Computes | 2024 | Leipzig | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | Not in the decode |
| Make | Porsche | Fuel | Electric |
| Model | Macan | Drive | AWD |
| Trim | Turbo Electric | Maker | DR. ING. H.C.F. PORSCHE AG |
| Body | Sport Utility Vehicle | Plant | Leipzig, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2024

**2** recalls listed by Transport Canada for this model year

### Visual system

2025182 9 Apr 2025

Issue: Under certain conditions, a software problem could cause the rearview camera not to work when the transmission is shifted into the reverse gear. Additionally, on certain vehicles, water could leak into the rearview camera. As a result, these issues could cause the rearview camera image not to display correctly or at all. Note: This recall only affects certain electric models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to update the reversing camera control unit software. Additionally, the dealer will inspect and, if necessary, replace the rearview and surround view cameras.

### Lights and instruments

2024722 26 Nov 2024

Issue: On a small number of vehicles, a software problem could cause the high beams to be too bright. Canadian regulations specify a maximum brightness for high beams. Safety Risk: High beams that are too bright could cause glare for oncoming drivers and increase the risk of a crash. Corrective Action: Porsche will notify owners by mail and advise you to take your vehicle to a dealership to reprogram the headlamp control unit.

Listed for the model year, not checked against your VIN. Porsche confirms which apply.
No online lookup from Porsche · call a Porsche dealer with your VIN.

## §3 VALUE [3]

This car asks $124,900[4], $54,905 over the median of $69,995[3].




| | |
|---|---|
| Lowest ask | $57,995 |
| Middle half | $61,900 – $89,995 |
| Median ask | $69,995 |
| This car | $124,900 |

Same model year · 25 live listings · as of 27 Oct 2026

### OTHER 2024 PORSCHE MACAN LISTINGS [4]

| | |
|---|---|
| Woodstock, ON · 43,449 km | $69,995 |
| Laval, QC · 37,128 km | $64,900 |
| Toronto, ON · 43,604 km | $57,995 |
| Toronto, ON · 38,616 km | $58,995 |
| Sainte-Rose, QC · 60,328 km | $66,900 |
| Toronto, ON · 22,418 km | $69,995 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Leipzig, Germany |
| 26 Nov 2024 | Transport Canada recall 2024722[2]<br>Issued for the model year · Lights and instruments |
| 9 Apr 2025 | Transport Canada recall 2025182[2]<br>Issued for the model year · Visual system |
| 14 Oct 2026 | Listed for sale, Mont-Royal, QC[4]<br>Holand Collection · asking $124,900 |
| 26 Oct 2026 | Listing last updated[4]<br>asking $124,900 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 25 live listings, as of 27 Oct 2026
[4] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.