Register entry, as of 26 October 2026 Listed for sale Record ID d665b0d7de66

2018 Porsche Macan Macan GTS

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WP1	AG2A5	7	J	L	B60588
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dr. Ing. H.C.F. Porsche Ag	Macan · 3.0 L	Computes	2018	Leipzig	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Porsche	Fuel	Gasoline
Model	Macan	Drive	AWD
Trim	Macan GTS	Maker	DR. ING. H.C.F. PORSCHE AG
Body	Sport Utility Vehicle	Plant	Leipzig, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/porsche/macan/2018

5 recalls listed by Transport Canada for this model year

Lights and instruments

2022487 31 Aug 2022

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters. As a result, the headlamps may be adjusted horizontally. Canadian regulations do not allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlamps that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealership to install caps over the headlamp adjustment screws.

Airbag

2021113 4 Mar 2021

Issue: On certain vehicles, the front passenger seat occupant sensor mat could stop working over time. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: The airbag warning light or passenger airbag OFF light will turn on if the sensor mat stops working. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion and occupant sensor mat.

Fuel system

2020054 13 Feb 2020

Issue: Over time, small cracks could develop in the fuel pump outlet. If this happens, there could be a fuel odour or fuel leak under the rear seat area. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Porsche will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump service cover. The fuel filter flanges will be inspected, and replaced if any cracks are found.

Label

2019192 18 Apr 2019

Issue: Certain wheels were made without a marking that is required by Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. The company has made changes to include the required marking on all new parts.

Accessories

2018661 28 Nov 2018

On certain vehicles equipped with an optional ski bag, the fastening strap for the ski bag may have been sewn with incorrect thread. This could cause the strap seams to tear in the event of crash, which would increase the risk of injury to the passengers. Correction: Dealers will replace the affected ski bags. Note: 72 of the affected ski bags may have been sold as an accessory part through Porsche Dealers.

> Listed for the model year, not checked against your VIN. Porsche confirms which apply.
> No online lookup from Porsche · call a Porsche dealer with your VIN.

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $32,989[5], $2,245 over the median of $30,744[4].

Lowest ask	$23,898
Middle half	$27,240 – $35,468
Median ask	$30,744
This car	$32,989

Same configuration · 12 live listings · as of 26 Oct 2026

OTHER 2018 PORSCHE MACAN LISTINGS [5]

Waterloo, ON · 79,000 km	$24,495
St. Catharines, ON · 78,540 km	$29,995
Calgary, AB · 67,712 km	$42,904
Sudbury, ON · 71,769 km	$29,991
Gatineau, QC · 217,136 km	$21,500
Trois-Rivières, QC · 172,403 km	$25,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant Leipzig, Germany
28 Nov 2018	Transport Canada recall 2018661[2] Issued for the model year · Accessories
18 Apr 2019	Transport Canada recall 2019192[2] Issued for the model year · Label
13 Feb 2020	Transport Canada recall 2020054[2] Issued for the model year · Fuel system
4 Mar 2021	Transport Canada recall 2021113[2] Issued for the model year · Airbag

31 Aug 2022	Transport Canada recall 2022487[2] Issued for the model year · Lights and instruments
25 Oct 2026	Listed for sale, Thetford mines, QC[5] Auto Quebec Occasion Thetford Mines · asking $32,989
26 Oct 2026	Listing last updated[5] asking $32,989

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 12 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.