

Register entry, as of 29 October 2026

Listed for sale

Record ID 78419a513017

# 2022 Audi RS Q8 quattro

4.0 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**WU1 ARBF1 5 N D 021242**

WMI 1-3

Audi Sport GmbH

DESCRIPTOR 4-8

RS Q8 · 4.0 L

CHECK 9

Computes

YEAR 10

2022

PLANT 11

Bratislava

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                      |
|------------|-----------------------|--------|----------------------|
| Model year | 2022                  | Engine | 4.0 L, 8 cylinders   |
| Make       | Audi                  | Fuel   | Gasoline             |
| Model      | RS Q8                 | Drive  | AWD                  |
| Trim       | quattro               | Maker  | Audi Sport GmbH      |
| Body       | Sport Utility Vehicle | Plant  | Bratislava, Slovakia |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/audi/rs-q8/2022](https://cardog.app/tools/recalls/audi/rs-q8/2022)

## 3 recalls listed by Transport Canada for this model year

### Visual system

2025713 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software.

### Visual system

2022611 26 Oct 2022

Issue: On certain vehicles, the infotainment main unit in the center console could fail. If this happens, the display screen will not turn on when you start the vehicle and the rearview camera image will not appear when backing up. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the infotainment unit.

### Visual system

2021642 20 Oct 2021

Issue: Under certain conditions, a software problem could cause a delay before the rearview camera image appears. Canadian regulations require the rearview image to display within 2 seconds of shifting the transmission into reverse gear. Safety Risk: A rearview camera that is slow to turn on could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle infotainment unit parameters.



Listed for the model year, not checked against your VIN. Audi confirms which apply.  
Check your VIN with Audi Canada or call a Audi dealer with your VIN.  
[www.audi.ca/en/recalls/](http://www.audi.ca/en/recalls/)

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$78,990<sup>[5]</sup>, \$3,500 under the median of \$82,490<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$78,990            |
| Middle half | \$80,740 – \$84,240 |
| Median ask  | \$82,490            |
| This car    | \$78,990            |

Same model year · 2 live listings · as of 29 Oct 2026

#### OTHER 2022 AUDI RS Q8 LISTINGS <sup>[5]</sup>

|                         |          |
|-------------------------|----------|
| Ottawa, ON · 51,496 km  | \$95,909 |
| Ottawa, ON · 51,496 km  | \$95,909 |
| Toronto, ON · 96,000 km | \$85,990 |

### §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2022        | Model year 2022 <sup>[1]</sup><br>Assembly plant Bratislava, Slovakia                       |
| 20 Oct 2021 | Transport Canada recall 2021642 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 26 Oct 2022 | Transport Canada recall 2022611 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 19 Dec 2025 | Transport Canada recall 2025713 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 12 Jan 2026 | Listed for sale, Woodbridge, ON <sup>[5]</sup><br>Palmary Motors · asking \$78,990          |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$78,990                                      |

### §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.



---

**SOURCES**

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                              |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                 |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

