

Register entry, as of 28 October 2026

Listed for sale

Record ID 8bf75a4a3a52

2019 Audi RS 3 quattro

2.5 L, 5 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**WUA BWGFF 5 K A 902252**

WMI 1-3

Audi Sport GmbH

DESCRIPTOR 4-8

RS 3 · 2.5 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ingolstadt

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2019	Engine	2.5 L, 5 cylinders
Make	Audi	Fuel	Gasoline
Model	RS 3	Drive	AWD
Trim	quattro	Maker	Audi Sport GmbH
Body	Sedan	Plant	Ingolstadt, Germany

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/audi/rs-3/2019

2 recalls listed by Transport Canada for this model year

Airbag

2021169 22 Mar 2021

Issue: On certain vehicles, the passenger occupant detection system (PODS) may not work properly. This could cause the airbag system to turn off the passenger-front airbag even when a person is seated in the front passenger seat. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off when it should be turned on could increase the risk of injury to a passenger in a crash. Corrective Actions: Audi will notify owners by mail. The corrective actions for this recall are under development. To reduce the safety risk, Audi recommends that if the PODS in your vehicle is not working properly, you should contact an Audi dealer for assistance right away and not transport a person in the front-passenger seat until the PODS has been repaired.

Airbag

2019308 19 Jun 2019

Issue: On certain vehicles, there could be a loose wiring connection for the passenger occupant detection system (PODS). This could cause the airbag system to turn off the passenger-front airbag even though the seat may be occupied. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to install a new connector for the passenger occupant detection system. The wiring will also be re-routed under the seat.

Listed for the model year, not checked against your VIN. Audi confirms which apply.

Check your VIN with Audi Canada or call a Audi dealer with your VIN.

www.audi.ca/en/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$48,888^[5], the median^[4].



Lowest ask	\$48,888
Middle half	\$48,888 – \$48,888
Median ask	\$48,888
This car	\$48,888

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Ingolstadt, Germany
19 Jun 2019	Transport Canada recall 2019308 ^[2] Issued for the model year · Airbag
22 Mar 2021	Transport Canada recall 2021169 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Burnaby, BC ^[5] Pioneer Motors Boundary · asking \$48,888
28 Oct 2026	Listing last updated ^[5] asking \$48,888

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

