

Register entry, as of 29 October 2026

Listed for sale

Record ID d496c1fe526b

2019 Audi RS 5 quattro

2.9 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WUA **RWAF5** **9** **K** **A** **904217**

WMI 1-3

Audi Sport GmbH

DESCRIPTOR 4-8

RS 5 · 2.9 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ingolstadt

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.9 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	RS 5	Drive	Not in the decode
Trim	quattro	Maker	Audi Sport GmbH
Body	Coupe	Plant	Ingolstadt, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/rs-5/2019

3 recalls listed by Transport Canada for this model year

Suspension

2022022 26 Jan 2022

Issue: On certain vehicles, the rear wheel alignment was not checked during recall 42L1 (Transport Canada Recall 2021-249). As a result, the steering could pull to one side or another and the tires could wear unevenly. If you continue to drive the vehicle in this condition, there may be reduced traction. Eventually, a tire could fail and lose air pressure. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and adjust the rear wheel alignment, as necessary. Additionally, the dealer will inspect the rear tires for premature and uneven wear due to this issue, and replace them if necessary.

Airbag

2021688 10 Nov 2021

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Additional note: For the 2020 model year A5 model, only the A5 Sportback is affected by this recall. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Audi will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the front passenger seat. Depending on the seat type, the dealer will either replace the seat heating mat including the connecting cable or the entire seat cover.

Electrical

2020604 9 Dec 2020

Issue: On certain vehicles, the cover for the positive battery terminal could be damaged in a rear crash. This can cause the car to lose electrical power. If this happens, it may not be possible to open the doors from the outside and/or the hazard lights may not work. Safety Risk: Doors that cannot be opened from the outside could increase the risk of injury after a crash. Hazard lights that do not work could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the plus (positive) terminal cover.




Listed for the model year, not checked against your VIN. Audi confirms which apply.
Check your VIN with Audi Canada or call a Audi dealer with your VIN.
www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$46,888^[5], the median^[4].



Lowest ask	\$40,995
Middle half	\$45,990 – \$51,943
Median ask	\$46,888
This car	\$46,888

Same model year · 7 live listings · as of 29 Oct 2026

OTHER 2019 AUDI RS 5 LISTINGS ^[5]

St-Jean-Sur-Richelieu, QC · 90,382 km	\$40,995
---------------------------------------	----------

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Ingolstadt, Germany
9 Dec 2020	Transport Canada recall 2020604 ^[2] Issued for the model year · Electrical
10 Nov 2021	Transport Canada recall 2021688 ^[2] Issued for the model year · Airbag
26 Jan 2022	Transport Canada recall 2022022 ^[2] Issued for the model year · Suspension
24 Oct 2026	Listed for sale, North York, ON ^[5] FARAZ AUTO SALES · asking \$46,888
28 Oct 2026	Listing last updated ^[5] asking \$46,888

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.
----------------	--



SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

