Register entry, as of 28 October 2026 Listed for sale Record ID 2ef239ad872d

2021 Volkswagen ID.4 Pro

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

WVG	CNPE2	7	M	P	061209
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Ag	ID.4	Computes	2021	Zwickau	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	Not in the decode
Make	Volkswagen	Fuel	Electric
Model	ID.4	Drive	AWD
Trim	Pro	Maker	VOLKSWAGEN AG
Body	Sport Utility Vehicle	Plant	Zwickau, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/id-4/2021

8 recalls listed by Transport Canada for this model year

Lights and instruments

2025099 26 Feb 2025

Issue: Under certain circumstances, a software problem could cause the "N" (Neutral) gear position not to display on the instrument cluster. As a result, you may not be aware when the transmission is in neutral. If this happens, and brakes or parking brake aren't used, the vehicle could roll away. Note: For the Q4 e-tron model, this recall affects both SUV and Sportback models. Safety Risk: A vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, the company recommends that you should use the parking brake and confirm the parking brake indicator light is on when you park. The company will notify owners by mail and advise you to take your vehicle to a dealership to update the brake control unit software.

Structure

2024502 4 Sep 2024

Issue: On certain vehicles, water could leak into the door handle(s). If this happens, the door(s) could open unexpectedly while driving. Note: This problem could cause a clicking noise that sounds like a door being locked or unlocked. Safety Risk: A door that opens while driving could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the door handles. The dealer will also update the vehicle software.

Airbag

2024485 29 May 2024

Issue: On certain vehicles, the owner's manual incorrectly describes the function of the passenger airbag indicator light. Safety Risk: This error does not affect the safety or function of the airbag. Corrective Actions: This is not a recall. The company has made changes to ensure that all new vehicles have owner manuals that correctly describe the function of the passenger airbag indicator light. The company will also instruct dealers to add an insert to correct owner's manuals for all unsold vehicles.

Visual system

2024275 15 May 2024

Issue: On certain vehicles, a software problem could cause the instrument cluster and center display to reset or not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer and certain warning lights and/or messages. In addition, the rearview camera image may not display when the transmission is shifted into the reverse gear. Safety Risk: Warnings and malfunction tell-tale information that don't display could increase the risk of a crash. Additionally, a rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could also increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software.

Structure

2023263 3 May 2023

Issue: On certain vehicles, water could leak into the door handle(s). If this happens, the door(s) could open unexpectedly while driving at speeds below 15 km/h. Note: This problem could cause a clicking noise that sounds like a door being locked or unlocked. Safety Risk: A door that opens while driving could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to inspect the door handles, and replace them if necessary. The dealer will also update the vehicle software.

High voltage

2023034 1 Feb 2023

Issue: On certain vehicles, a software problem could cause the high-voltage battery management control module to reset or the pulse inverter to deactivate. If this happens while driving, the electric motor would not supply power to the wheels. Note: If this happens, you may see a warning message on the instrument panel. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the high-voltage battery control unit and the pulse inverter control unit software.

2 more on the model-year record, cardog.app/tools/recalls/volkswagen/id-4/2021

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,995[5], $3,752 under the median of $28,747[4].

Lowest ask	$24,995
Middle half	$27,710 – $29,746
Median ask	$28,747
This car	$24,995

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2021 VOLKSWAGEN ID.4 LISTINGS [5]

Laval, QC · 52,799 km	$27,448
Montréal, QC · 85,063 km	$28,495
Terrebonne, QC · 41,979 km	$32,995
Blainville, QC · 82,101 km	$28,999
Saint-Laurent, QC · 35,000 km	$29,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Zwickau, Germany
16 Mar 2022	Transport Canada recall 2022123[2] Issued for the model year · High voltage
2 Nov 2022	Transport Canada recall 2022631[2] Issued for the model year · Airbag
1 Feb 2023	Transport Canada recall 2023034[2] Issued for the model year · High voltage
3 May 2023	Transport Canada recall 2023263[2] Issued for the model year · Structure
15 May 2024	Transport Canada recall 2024275[2] Issued for the model year · Visual system
29 May 2024	Transport Canada recall 2024485[2] Issued for the model year · Airbag
4 Sep 2024	Transport Canada recall 2024502[2] Issued for the model year · Structure
26 Feb 2025	Transport Canada recall 2025099[2] Issued for the model year · Lights and instruments
29 Jul 2026	Listed for sale, St-Jean-Sur-Richelieu, QC[5] Haut-Richelieu Volkswagen · asking $24,995
28 Oct 2026	Listing last updated[5] asking $24,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.