

2014 Volkswagen Tiguan 4-Motion

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVG JV3AX 4 E W 577472

WMI 1-3

Volkswagen Ag

DESCRIPTOR 4-8

Tiguan · 2.0 L

CHECK 9

Computes

YEAR 10

2014

PLANT 11

Wolfsburg

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4-Motion	Maker	VOLKSWAGEN AG
Body	Sport Utility Vehicle	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2014

4 recalls listed by Transport Canada for this model year

Lights and instruments

2020468 6 Oct 2020

Issue: On certain vehicles, the ESC warning light may not remain on if a fault was detected on the previous key cycle. Instead, the warning light does not turn on until the vehicle starts to move. Canadian regulations require that the ESC warning light must turn on when the vehicle is started (under these conditions). Note: This problem can only happen if there is a fault related to the power steering system. The power steering warning light would stay on to advise that there is a fault with the steering system. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to the vehicle software to correct this issue on all new vehicles.

Airbag

2015347 31 Jul 2015

On one certain vehicle, the driver front airbag module (manufactured by TRW) may not have been properly welded during the manufacturing process. In the event of a crash, the air bag may not unfold properly during deployment, increasing the risk of injury. Correction: Dealers will replace the driver side airbag.

Seats and restraints

2015344 31 Jul 2015

On certain vehicles, the steering wheel clock spring could become contaminated with long hair or long fibers which may cause a displacement of the internal guide loops. When the guide loops are dragged out of position, they may apply tension to the internal flat cable and cause it to tear. Should the cable tear, the electrical connection to the driver's front airbag may be lost, causing the airbag monitoring indicator light to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will install a cover of a different design to help prevent clock spring contamination caused by hair or other fibers. In instances where the vehicle has an airbag light on (and diagnosis confirms the steering wheel clock spring requires replacement), dealers will install a new steering wheel clock spring.



Fuel system

2014307 22 Jul 2014


On certain vehicles, deposits may collect on fuel pump connections and reduce fuel pump performance. This could cause the engine to stall, resulting in a loss of motive power and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update vehicle software to increase fuel pump pressure in order to prevent deposits from forming.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$13,507^[5], \$4,010 over the median of \$9,497^[4].



Lowest ask	\$4,444
Middle half	\$7,620 – \$13,130
Median ask	\$9,497
This car	\$13,507

Same configuration · 18 live listings · as of 29 Oct 2026

OTHER 2014 VOLKSWAGEN TIGUAN LISTINGS [5]

Thornhill, ON · 176,704 km	\$5,600
Thornhill, ON · 94,836 km	\$10,688
Courtenay, BC · 174,893 km	\$15,995
Saint-Hyacinthe, QC · 188,910 km	\$4,444
Beloeil, QC · 208,011 km	\$7,495
Montréal, QC · 77,567 km	\$8,995

§4 EVENTS

2014	Model year 2014 ^[1] Assembly plant Wolfsburg, Germany
22 Jul 2014	Transport Canada recall 2014307 ^[2] Issued for the model year · Fuel system
31 Jul 2015	Transport Canada recall 2015347 ^[2] Issued for the model year · Airbag
31 Jul 2015	Transport Canada recall 2015344 ^[2] Issued for the model year · Seats and restraints
6 Oct 2020	Transport Canada recall 2020468 ^[2] Issued for the model year · Lights and instruments
26 Oct 2026	Listed for sale, Sherwood Park, AB ^[5] Sherwood Park Volkswagen · asking \$13,507



29 Oct 2026 Listing last updated^[5]
asking \$13,507

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 18 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

