Register entry, as of 28 October 2026 Listed for sale Record ID 9863f7c9b791

2015 Volkswagen Tiguan 4-Motion

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVG	JV7AX	5	F	W	579921
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Volkswagen Ag	Tiguan · 2.0 L	Computes	2015	Wolfsburg	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4-Motion	Maker	VOLKSWAGEN AG
Body	Sport Utility Vehicle	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2015

4 recalls listed by Transport Canada for this model year

Lights and instruments

2020468 6 Oct 2020

Issue: On certain vehicles, the ESC warning light may not remain on if a fault was detected on the previous key cycle. Instead, the warning light does not turn on until the vehicle starts to move. Canadian regulations require that the ESC warning light must turn on when the vehicle is started (under these conditions). Note: This problem can only happen if there is a fault related to the power steering system. The power steering warning light would stay on to advise that there is a fault with the steering system. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to the vehicle software to correct this issue on all new vehicles.

Airbag

2019352 17 Jul 2019

Issue: On certain vehicles, the airbag control unit may contain a defective capacitor. If the capacitor fails, it could result in a deployment of the airbags and/or seat belt pretensioners without a crash. This could also cause the airbag system to not deploy in the event of a crash. Safety Risk: Airbags or seat belt pretensioners that deploy without a crash could create a risk of injury and also increase the risk of a crash. Airbags that do not deploy in a crash could create an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to have updated airbag control unit software installed and, if necessary, the airbag control unit will be replaced.

Airbag

2016041 27 Jan 2016

On certain vehicles, the driver and/or right front passenger seat-mounted airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of either of the seat-mounted airbags to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the affected driver and/or passenger seat side airbag modules with new production modules.

Label

2015209 15 May 2015

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 120 - Tire Selection and Rims. The certification label is missing the recommended tire pressure information. Also, incorrect gross vehicle weight rating / gross axle weight rating information may have been printed on the label. This could lead to tire underinflation and/or vehicle overloading, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will apply a revised label.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,990[5], $1,998 under the median of $10,988[4].



Lowest ask	$5,999
Middle half	$8,824 – $13,199
Median ask	$10,988
This car	$8,990

Same configuration · 31 live listings · as of 28 Oct 2026

OTHER 2015 VOLKSWAGEN TIGUAN LISTINGS [5]

Edmonton, AB · 143,316 km	$12,888
Carbonear, NL · 99,000 km	$8,990
Kentville, NS · 150,566 km	$10,421
Clarenville, NL · 99,000 km	$7,990
Calgary, AB · 171,906 km	$12,898
Yarmouth, NS · 150,566 km	$10,421

§4 EVENTS

2015	Model year 2015[1] Assembly plant Wolfsburg, Germany
15 May 2015	Transport Canada recall 2015209[2] Issued for the model year · Label
27 Jan 2016	Transport Canada recall 2016041[2] Issued for the model year · Airbag
17 Jul 2019	Transport Canada recall 2019352[2] Issued for the model year · Airbag
6 Oct 2020	Transport Canada recall 2020468[2] Issued for the model year · Lights and instruments

25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC[5] Prilo Occasion · asking $8,990
28 Oct 2026	Listing last updated[5] asking $8,990

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 31 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.