Register entry, as of 29 October 2026 Listed for sale Record ID 4819ef501129

# 2016 Volkswagen Tiguan

2.0 L, 4 cylinders · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
|---|---|---|---|---|---|
| WVG | JV7AX | 6 | G | W | 541941 |
| Volkswagen Ag | Tiguan · 2.0 L | Computes | 2016 | Wolfsburg | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Tiguan | Drive | Not in the decode |
| Trim | Not in the decode | Maker | VOLKSWAGEN AG |
| Body | Not in the decode | Plant | Wolfsburg, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2016

**3** recalls listed by Transport Canada for this model year

### Lights and instruments

2020468 6 Oct 2020

Issue: On certain vehicles, the ESC warning light may not remain on if a fault was detected on the previous key cycle. Instead, the warning light does not turn on until the vehicle starts to move. Canadian regulations require that the ESC warning light must turn on when the vehicle is started (under these conditions). Note: This problem can only happen if there is a fault related to the power steering system. The power steering warning light would stay on to advise that there is a fault with the steering system. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to the vehicle software to correct this issue on all new vehicles.

### Airbag

2019352 17 Jul 2019

Issue: On certain vehicles, the airbag control unit may contain a defective capacitor. If the capacitor fails, it could result in a deployment of the airbags and/or seat belt pretensioners without a crash. This could also cause the airbag system to not deploy in the event of a crash. Safety Risk: Airbags or seat belt pretensioners that deploy without a crash could create a risk of injury and also increase the risk of a crash. Airbags that do not deploy in a crash could create an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to have updated airbag control unit software installed and, if necessary, the airbag control unit will be replaced.

### Structure

2016319 22 Jun 2016

On certain vehicles, rear door child safety locks could disengage due to external vehicle vibration (such as when closing a door). This would render it possible for a child to unintentionally open a door, increasing the risk of injury. Correction: Dealers will inspect and, if necessary, replace the child locks. Note: This recall affects Golf R models only.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $16,995[5], $6,003 over the median of $10,992[4].

| | |
|---|---|
| Lowest ask | $6,495 |
| Middle half | $8,912 – $12,995 |
| Median ask | $10,992 |
| This car | $16,995 |

Same configuration · 32 live listings · as of 29 Oct 2026

### OTHER 2016 VOLKSWAGEN TIGUAN LISTINGS [5]

| | |
|---|---|
| Sherbrooke, QC · 168,539 km | $10,988 |
| Candiac, QC · 183,368 km | $6,795 |
| Vaudreuil-Dorion, QC · 183,368 km | $6,795 |
| Cambridge, ON · 130,091 km | $13,989 |
| Markham, ON · 81,659 km | $13,021 |
| Toronto, ON · 154,311 km | $5,995 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Wolfsburg, Germany |
| 22 Jun 2016 | Transport Canada recall 2016319[2]<br>Issued for the model year · Structure |
| 17 Jul 2019 | Transport Canada recall 2019352[2]<br>Issued for the model year · Airbag |
| 6 Oct 2020 | Transport Canada recall 2020468[2]<br>Issued for the model year · Lights and instruments |
| 26 Oct 2026 | Listed for sale, Richmond, BC[5]<br>Volkswagen of Richmond · asking $16,995 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $16,995 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 32 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.