Register entry, as of 29 October 2026 Listed for sale Record ID d1ebbcc53d44

# 2022 Volkswagen ID.4 Pro S

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| WVG | UNPE2 | 7 | N | P | 072880 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Volkswagen Ag | ID.4 | Computes | 2022 | Zwickau | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | Not in the decode |
| Make | Volkswagen | Fuel | Electric |
| Model | ID.4 | Drive | AWD |
| Trim | Pro S | Maker | VOLKSWAGEN AG |
| Body | Sport Utility Vehicle | Plant | Zwickau, Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/id-4/2022

**6** recalls listed by Transport Canada for this model year

### Lights and instruments

2025099 26 Feb 2025

Issue: Under certain circumstances, a software problem could cause the "N" (Neutral) gear position not to display on the instrument cluster. As a result, you may not be aware when the transmission is in neutral. If this happens, and brakes or parking brake aren't used, the vehicle could roll away. Note: For the Q4 e-tron model, this recall affects both SUV and Sportback models. Safety Risk: A vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, the company recommends that you should use the parking brake and confirm the parking brake indicator light is on when you park. The company will notify owners by mail and advise you to take your vehicle to a dealership to update the brake control unit software.

### Structure

2024502 4 Sep 2024

Issue: On certain vehicles, water could leak into the door handle(s). If this happens, the door(s) could open unexpectedly while driving. Note: This problem could cause a clicking noise that sounds like a door being locked or unlocked. Safety Risk: A door that opens while driving could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the door handles. The dealer will also update the vehicle software.

### Visual system

2024275 15 May 2024

Issue: On certain vehicles, a software problem could cause the instrument cluster and center display to reset or not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer and certain warning lights and/or messages. In addition, the rearview camera image may not display when the transmission is shifted into the reverse gear. Safety Risk: Warnings and malfunction tell-tale information that don't display could increase the risk of a crash. Additionally, a rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could also increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software.

### Structure

2023263 3 May 2023

Issue: On certain vehicles, water could leak into the door handle(s). If this happens, the door(s) could open unexpectedly while driving at speeds below 15 km/h. Note: This problem could cause a clicking noise that sounds like a door being locked or unlocked. Safety Risk: A door that opens while driving could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to inspect the door handles, and replace them if necessary. The dealer will also update the vehicle software.

### Visual system

2022630 2 Nov 2022

Issue: On certain vehicles, after shifting into reverse or manually activating the parking function, the rearview camera image may not display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rearview camera.

### High voltage

2022123 16 Mar 2022

Issue: On a small number of vehicles, a problem with the high-voltage battery may cause the electric motor to shut down. If this happens, there would be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the affected battery cell modules.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $24,995[5], $6,400 under the median of $31,395[4].

| | |
|---|---|
| Lowest ask | $24,995 |
| Middle half | $29,788 – $34,873 |
| Median ask | $31,395 |
| This car | $24,995 |

Same configuration · 10 live listings · as of 28 Oct 2026

#### OTHER 2022 VOLKSWAGEN ID.4 LISTINGS [5]

| | |
|---|---|
| Victoriaville, QC · 52,154 km | $31,995 |
| Laval, QC · 64,041 km | $29,717 |
| Waterloo, ON · 68,030 km | $32,995 |
| Granby, QC · 57,495 km | $30,795 |
| Vancouver, BC · 61,777 km | $37,985 |
| Saint-Jérôme, QC · 88,581 km | $26,490 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Zwickau, Germany |
| 16 Mar 2022 | Transport Canada recall 2022123[2]<br>Issued for the model year · High voltage |

| | |
|---|---|
| 2 Nov 2022 | Transport Canada recall 2022630[2]<br>Issued for the model year · Visual system |
| 3 May 2023 | Transport Canada recall 2023263[2]<br>Issued for the model year · Structure |
| 15 May 2024 | Transport Canada recall 2024275[2]<br>Issued for the model year · Visual system |
| 4 Sep 2024 | Transport Canada recall 2024502[2]<br>Issued for the model year · Structure |
| 26 Feb 2025 | Transport Canada recall 2025099[2]<br>Issued for the model year · Lights and instruments |
| 26 Oct 2026 | Listed for sale, Trois-Rivières, QC[5]<br>Acura Trois-Rivières · asking $24,995 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $24,995 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.