Register entry, as of 23 November 2026 Listed for sale Record ID e5614f1d1729

2010 Volkswagen Eos Turbo, Komfort

2.0 L, 4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVW	BA7AH	8	A	V	009181
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Ag	Eos · 2.0 L	Computes	2010	Palmela	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Eos	Drive	Not in the decode
Trim	Turbo, Komfort	Maker	VOLKSWAGEN AG
Body	Convertible	Plant	Palmela, Portugal

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/eos/2010

3 recalls listed by Transport Canada for this model year

Airbag

2018111 6 Mar 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the driver frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the driver frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This recall supersedes the Volkswagen brand vehicles subject to recall 2016-064 (Volkswagen Recall 69M9). Volkswagen vehicles completed under the previous 2016-064 recall require repair under this recall, as the previous recall remedy was an interim repair. Interim repair parts must be replaced with final repair parts.

Airbag

2016064 9 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver airbag inflator. Note: This campaign only affects the Audi A5 and Audi S5 Cabriolet models.

Powertrain 2009249 20 Aug 2009

On certain Audi A3, TT, TT Roadster, and Volkswagen EOS, Golf wagon, GTI, Jetta and Jetta wagon equipped with a Direct-Shift Gearbox (DSG), the wiring harness of a temperature sensor in the DSG may have connector wires that were insufficiently crimped during assembly. As such, the temperature sensor could falsely detect a high gearbox oil temperature, causing the transmission to abruptly shift to the Neutral position. A loss of propulsion, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing personal injury or death. Correction: Dealers will reprogram the transmission control module with updated software..

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,495[5], $1,000 under the median of $8,495[4].



Lowest ask	$8,495
Middle half	$8,495 – $8,495
Median ask	$8,495
This car	$7,495

Same model year · 1 live listings · as of 23 Nov 2026

§4 EVENTS

2010	Model year 2010[1] Assembly plant Palmela, Portugal
20 Aug 2009	Transport Canada recall 2009249[2] Issued for the model year · Powertrain
9 Feb 2016	Transport Canada recall 2016064[2] Issued for the model year · Airbag
6 Mar 2018	Transport Canada recall 2018111[2] Issued for the model year · Airbag
31 Oct 2026	Listed for sale, St-Jean-Sur-Richelieu, QC[5] Haut-Richelieu Volkswagen · asking $7,495
23 Nov 2026	Listing last updated[5] asking $7,495

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 1 live listings, as of 23 Nov 2026

[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.