Register entry, as of 29 October 2026 Listed for sale Record ID f65c5d786357

2022 Volkswagen Golf R

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVW	EB7CD	4	N	W	120508
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Volkswagen Ag	Golf R · 2.0 L	Computes	2022	Wolfsburg	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Golf R	Drive	Not in the decode
Trim	Not in the decode	Maker	VOLKSWAGEN AG
Body	Hatchback	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf-r/2022

6 recalls listed by Transport Canada for this model year

Visual system

2024365 27 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image to be delayed or not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment software.

Airbag

2024485 29 May 2024

Issue: On certain vehicles, the owner's manual incorrectly describes the function of the passenger airbag indicator light. Safety Risk: This error does not affect the safety or function of the airbag. Corrective Actions: This is not a recall. The company has made changes to ensure that all new vehicles have owner manuals that correctly describe the function of the passenger airbag indicator light. The company will also instruct dealers to add an insert to correct owner's manuals for all unsold vehicles.

Visual system

2022630 2 Nov 2022

Issue: On certain vehicles, after shifting into reverse or manually activating the parking function, the rearview camera image may not display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rearview camera.

Engine

2022533 21 Sep 2022

Issue: On certain vehicles, the radiator may not be attached correctly. As a result, a coolant hose could be damaged by contact with the serpentine belt pulley and create a coolant leak. If this happens, coolant could spill onto the road and cause a red warning light to turn on in the instrument cluster. If you ignore the warning light and continue driving, the engine could overheat. Safety Risk: A coolant leak could create a hazard for other road users. Additionally, an engine that overheats could create the risk of a fire. Corrective Action: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to ensure that the radiator is attached correctly. If it is loose, the coolant hose and serpentine belt will also be checked for damage, and replaced if necessary.

Visual system

2022402 27 Jul 2022

Issue: On certain vehicles, the touch switch that controls the sunroof may be too sensitive. As a result, the sunroof switch does not pass certain tests under Canadian safety regulations. Safety Risk: A sunroof that closes accidentally could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and advise you to contact a dealership to make an appointment to replace the sunroof switch.

Engine

2022122 16 Mar 2022

Issue: The engine cover may come loose in certain driving conditions. If this happens, the engine cover could contact hot surfaces in the engine compartment and melt. Safety Risk: An engine cover that melts onto a hot surface could create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to remove the engine cover. Volkswagen will send you another notice once a replacement engine cover is available, and will ask you to take your vehicle to a dealer to have it installed.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $40,998[5], $1,506 over the median of $39,492[4].

Lowest ask	$36,277
Middle half	$38,666 – $40,992
Median ask	$39,492
This car	$40,998

Same model year · 8 live listings · as of 29 Oct 2026

OTHER 2022 VOLKSWAGEN GOLF R LISTINGS [5]

Port Coquitlam, BC · 59,185 km	$40,990
Whitby, ON · 79,892 km	$39,988
Belleville, ON · 99,991 km	$38,000
Amos, QC · 81,736 km	$38,995
Waterloo, ON · 40,727 km	$41,995
Kitchener, ON · 40,727 km	$41,995

§4 EVENTS

2022 Model year 2022[1]
Assembly plant Wolfsburg, Germany

16 Mar 2022	Transport Canada recall 2022122[2] Issued for the model year · Engine
27 Jul 2022	Transport Canada recall 2022402[2] Issued for the model year · Visual system
21 Sep 2022	Transport Canada recall 2022533[2] Issued for the model year · Engine
2 Nov 2022	Transport Canada recall 2022630[2] Issued for the model year · Visual system
29 May 2024	Transport Canada recall 2024485[2] Issued for the model year · Airbag
27 Jun 2024	Transport Canada recall 2024365[2] Issued for the model year · Visual system
28 Oct 2026	Listed for sale, Oakville, ON[5] Lexus Of Oakville · asking $40,998

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.