

Register entry, as of 28 October 2026

Listed for sale

Record ID 0a52248af32b

2009 Volkswagen GTI

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVW HV71K 1 9 W 127489

WMI 1-3

Volkswagen Ag

DESCRIPTOR 4-8

GTI · 2.0 L

CHECK 9

Computes

YEAR 10

2009

PLANT 11

Wolfsburg

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	GTI	Drive	Not in the decode
Trim	Not in the decode	Maker	VOLKSWAGEN AG
Body	Hatchback	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/gti/2009

3 recalls listed by Transport Canada for this model year

Brakes 2016629 14 Dec 2016

On certain vehicles, a fault within the antilock brake system (ABS) may cause the module to fail during ABS and/or electronic stability control (ESC) activation. This will cause warning lights for ABS, brake and the ESC systems to illuminate. If this happens, the brake system related vehicle stabilizing functions (ABS/ESC) may not be available, increasing the risk of a loss of vehicle control and could lead to a crash causing injury and/or property damage. Correction: Dealers will update the ABS control module with improved diagnostic capability to detect insufficient PCU ground connection. ABS modules with insufficient ground connections will be replaced.

Electrical 2014069 5 Mar 2014

On certain vehicles, a fuse can overheat and damage the fuse box, causing a partial loss of exterior vehicle lighting. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install a fuse of an updated design.

Powertrain 2009249 20 Aug 2009

On certain Audi A3, TT, TT Roadster, and Volkswagen EOS, Golf wagon, GTI, Jetta and Jetta wagon equipped with a Direct-Shift Gearbox (DSG), the wiring harness of a temperature sensor in the DSG may have connector wires that were insufficiently crimped during assembly. As such, the temperature sensor could falsely detect a high gearbox oil temperature, causing the transmission to abruptly shift to the Neutral position. A loss of propulsion, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing personal injury or death. Correction: Dealers will reprogram the transmission control module with updated software..

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.

Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.


www.vw.ca/en/owners-and-drivers/recalls.html



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$3,000^[5], the median^[4].



Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2009	Model year 2009 ^[1] Assembly plant Wolfsburg, Germany
20 Aug 2009	Transport Canada recall 2009249 ^[2] Issued for the model year · Powertrain
5 Mar 2014	Transport Canada recall 2014069 ^[2] Issued for the model year · Electrical
14 Dec 2016	Transport Canada recall 2016629 ^[2] Issued for the model year · Brakes
23 Sep 2026	Listed for sale, Whitby, ON ^[5] Owasco Volkswagen And Audi · asking \$3,000
28 Oct 2026	Listing last updated ^[5] asking \$3,000

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

