

Register entry, as of 27 October 2026

Listed for sale

Record ID 0710a45f82cf

2019 Volvo V60 Inscription

2.0 L, 4 cylinders · AWD · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV1 A22SL 4 K 2 027673

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

V60 · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Belgium

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	V60	Drive	AWD
Trim	Inscription	Maker	VOLVO CAR CORPORATION
Body	Wagon	Plant	Belgium

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/v60/2019

5 recalls listed by Transport Canada for this model year

Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

Electrical

2021345 2 Jun 2021

Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.

Brakes

2020099 13 Mar 2020

Issue: On certain vehicles, the automatic emergency braking system (AEB) may not apply the brakes automatically when it detects a possible collision. In addition, the system may not warn of a potential crash with a non-moving vehicle or object. Note: The regular brake system and all other functions in the vehicle are not affected by this problem. Safety Risk: The AEB system may not provide driver warnings and apply the brakes automatically to help avoid a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle software.



Label

2018731 21 Dec 2018

Certain vehicles do not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 110 – Tire Selection and Rims. The tire certification label on the B-pillar incorrectly states a front wheel size of 19 inches, when it should read as 18 inches. In the unlikely event that incorrectly sized wheels and/or tires were installed, vehicle stability could be affected, which could increase the risk of a crash causing injury and/or damage to property. Correction: Volvo will install a corrected certification label on affected vehicles.

Accessories

2018618 9 Nov 2018

On certain vehicles, the Telematics and Driver Support Systems may not function as designed due to a software error. In the event of a crash, this could mean that the Emergency Assist system would not alert Volvo and provide the GPS coordinates of the vehicle. This could create a risk of no response from emergency services. Correction: Dealers will update vehicle software.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.


Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$39,000^[5], \$12,005 over the median of \$26,995^[4].



Lowest ask	\$16,017
Middle half	\$23,500 – \$30,746
Median ask	\$26,995
This car	\$39,000

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2019 VOLVO V60 LISTINGS [5]

Perth, ON · 188,624 km	\$16,017
Lachute, QC · 136,375 km	\$25,995
Hamilton, ON · 152,979 km	\$27,995

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Belgium
9 Nov 2018	Transport Canada recall 2018618 ^[2] Issued for the model year · Accessories
21 Dec 2018	Transport Canada recall 2018731 ^[2] Issued for the model year · Label
13 Mar 2020	Transport Canada recall 2020099 ^[2] Issued for the model year · Brakes
2 Jun 2021	Transport Canada recall 2021345 ^[2] Issued for the model year · Electrical



20 Oct 2022	Transport Canada recall 2022595 ^[2] Issued for the model year · Visual system
16 Dec 2025	Listed for sale, Oakville, ON ^[5] Medallion Motors Inc · asking \$39,000
27 Oct 2026	Listing last updated ^[5] asking \$39,000

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

