

Register entry, as of 26 October 2026

Listed for sale

Record ID d5089e32af06

2008 Volvo S80

3.2 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV1 AH982 X 8 1 051299

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

S80 · 3.2 L

CHECK 9

Computes

YEAR 10

2008

PLANT 11

Torslanda

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.2 L, 6 cylinders
Make	Volvo	Fuel	Gasoline
Model	S80	Drive	AWD
Trim	Not in the decode	Maker	VOLVO CAR CORPORATION
Body	Sedan	Plant	Torslanda, Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/s80/2008

6 recalls listed by Transport Canada for this model year

Seats and restraints

2020298 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

Accessories

2010396 8 Nov 2010

On certain vehicles, there is a possibility of overheating issues of batteries in the Garmin nüvi® 760 when certain batteries manufactured within a limited date code range are used in certain Garmin nüvi® 760 models with a specific printed circuit board (PCB) design. The interaction of these factors can, in some circumstances, increase the possibility of overheating, which may lead to a fire. Correction: Dealers will direct customers who have an affected unit to the Garmin Web site, which explains how to verify if their units are involved and includes procedures to follow for product exchange.

Fuel system

2009255 8 Sep 2009

On certain vehicles, the software within the Central Electronic Module (CEM) may not send a signal to the fuel Pump Electronic Module (PEM). This missing signal to the PEM inhibits the start of the fuel pump. The driver may be able to start the engine in spite of the fuel pump not being activated due to residual pressure in the fuel system. In some cases, the driver may be able to drive the vehicle a short distance at idle. However, the engine will eventually stall. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will upgrade the CEM software.



Engine

2009179 10 Jun 2009

On certain vehicles, the engine cooling fan may stop working due to a software programming error in the Fan Control Module (FCM). Depending on conditions, the driver may experience reduced air conditioning performance and/or rapid increase in engine coolant temperature. This could result in a loss of cooling system function and engine break down. The driver may not have sufficient time to react to the warning light(s) or the text message in the instrument panel, increasing the risk of a crash causing personal injury or death. Correction: Dealers will replace the Fan Control Module.

Electrical

2009124 23 Apr 2009

On certain vehicles, the diagnostic software in the Central Electronic Module (CEM) may cause a malfunction of the windshield wiper functionality. If this occurs, the windshield wipers may not operate when activated; or in certain cases the windshield wipers may activate when not switched on. Should this occur during a rainy/snowy day, it could increase the risk of a crash, causing property damage, personal injury or death. Correction: Dealers will install updated CEM software.

Engine

2008150 2 May 2008

Certain vehicles may have been inadvertently assembled with incorrect engine mount bolts. The longer bolts do not provide adequate clamping force to the bracket. In the worst case, the aluminium bracket for the engine mount will break, allowing the engine to contact the sub frame, ultimately resulting in reduced engine torque or stalling. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will inspect the engine mount bolts for specific markings and, if required, replace the bracket and bolts.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$3,995^[5], the median^[4].



Lowest ask	\$3,995
Middle half	\$3,995 – \$3,995
Median ask	\$3,995
This car	\$3,995

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

2008 Model year 2008^[1]
Assembly plant Torslanda, Sweden

2 May 2008 Transport Canada recall 2008150^[2]
Issued for the model year · Engine

23 Apr 2009 Transport Canada recall 2009124^[2]
Issued for the model year · Electrical

10 Jun 2009 Transport Canada recall 2009179^[2]
Issued for the model year · Engine



8 Sep 2009	Transport Canada recall 2009255 ^[2] Issued for the model year · Fuel system
8 Nov 2010	Transport Canada recall 2010396 ^[2] Issued for the model year · Accessories
30 Jun 2020	Transport Canada recall 2020298 ^[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Sainte-Rose, QC ^[5] Demirci Auto · asking \$3,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

