

Register entry, as of 28 October 2026

Listed for sale

Record ID 96ba66f909aa

# 2021 Volvo XC40 R-Design

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**YV4 162UM 2 M 2 527699**

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC40 · 2.0 L

CHECK 9

Computes

YEAR 10

2021

PLANT 11

Belgium

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                       |
|------------|-----------------------|--------|-----------------------|
| Model year | 2021                  | Engine | 2.0 L, 4 cylinders    |
| Make       | Volvo                 | Fuel   | Gasoline              |
| Model      | XC40                  | Drive  | Not in the decode     |
| Trim       | R-Design              | Maker  | VOLVO CAR CORPORATION |
| Body       | Sport Utility Vehicle | Plant  | Belgium               |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volvo/xc40/2021](https://cardog.app/tools/recalls/volvo/xc40/2021)

## 5 recalls listed by Transport Canada for this model year

### Visual system

2025718 23 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Note: This recall replaces Transport Canada recall no. 2025-233. Vehicles that were repaired under that recall also require this repair. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Volvo dealership.

### Visual system

2025233 1 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Volvo dealership.

### Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.



## Electrical

2022216 28 Apr 2022

Issue: On certain XC40 Recharge models, water may enter the wire harness for the accelerator pedal. If this happens, the accelerator pedal may not work properly. This problem could also cause the vehicle not to start. Safety Risk: An accelerator pedal that does not work properly could cause a loss of power to the wheels or a sudden unintended acceleration. Both could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealership to add a cable splice to the accelerator pedal wiring.

## Seats and restraints

2021540 1 Sep 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

[www.volvocars.com/en-ca/l/recall-information/](http://www.volvocars.com/en-ca/l/recall-information/)

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$33,255<sup>[5]</sup>, \$4,624 over the median of \$28,631<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$19,863            |
| Middle half | \$23,737 – \$29,997 |
| Median ask  | \$28,631            |
| This car    | \$33,255            |

Same model year · 11 live listings · as of 28 Oct 2026

## OTHER 2021 VOLVO XC40 LISTINGS [5]

|                                           |          |
|-------------------------------------------|----------|
| St-Hubert, QC · 73,830 km                 | \$29,995 |
| Sainte-Rose – Laval, QC · 93,283 km       | \$23,785 |
| Calgary, AB · 69,361 km                   | \$29,999 |
| North Vancouver, BC · 71,686 km           | \$29,505 |
| Sainte-Rose, QC · 50,100 km               | \$31,881 |
| Salaberry-De-Valleyfield, QC · 119,068 km | \$29,995 |

## §4 EVENTS

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2021        | Model year 2021 <sup>[1]</sup><br>Assembly plant Belgium                                           |
| 1 Sep 2021  | Transport Canada recall 2021540 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 28 Apr 2022 | Transport Canada recall 2022216 <sup>[2]</sup><br>Issued for the model year · Electrical           |



|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 20 Oct 2022 | Transport Canada recall 2022595 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 1 May 2025  | Transport Canada recall 2025233 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 15 Oct 2025 | Listed for sale, Ajax, ON <sup>[5]</sup><br>Volvo Cars Of Lakeridge · asking \$33,255       |
| 23 Dec 2025 | Transport Canada recall 2025718 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$33,255                                      |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 11 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

