

Register entry, as of 27 October 2026

Listed for sale

Record ID 1605ce4693da

# 2016 Volvo XC60 SV33 Premier

2.0 L, 4 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**YV4 49MDK 1 G 2 863461**

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC60 · 2.0 L

CHECK 9

Computes

YEAR 10

2016

PLANT 11

Gent Plant

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                       |
|------------|-----------------------|--------|-----------------------|
| Model year | 2016                  | Engine | 2.0 L, 4 cylinders    |
| Make       | Volvo                 | Fuel   | Gasoline              |
| Model      | XC60                  | Drive  | FWD                   |
| Trim       | SV33 Premier          | Maker  | VOLVO CAR CORPORATION |
| Body       | Sport Utility Vehicle | Plant  | Gent Plant, Belgium   |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volvo/xc60/2016](https://cardog.app/tools/recalls/volvo/xc60/2016)

## 3 recalls listed by Transport Canada for this model year

### Seats and restraints

2020298 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

### Seats and restraints

2016534 28 Oct 2016

On certain vehicles, the front passenger seatbelt buckle stud may not have been punched correctly during manufacturing. This may cause a separation between the buckle and the seat belt bracket, which could result in the belt not adequately restraining the seat occupant in a crash, increasing the risk of injury and/or damage to property. Correction: Dealers will inspect the front passenger seat belt buckle stud, and replace the seatbelt buckle as necessary.

### Electrical

2015388 2 Sep 2015

On certain vehicles with an automatic stop-start function, in certain stop and go driving situations, the starter motor fuse may become overloaded (blown fuse). This could lead to the inability to restart the engine following an engine shutdown by the start-stop system, increasing the risk of crash causing injury in a traffic situation. Correction: Dealers will replace the starter motor fuse with a higher amperage rated fuse.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

[www.volvocars.com/en-ca/l/recall-information/](http://www.volvocars.com/en-ca/l/recall-information/)

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>



## §3 VALUE [4]

This car asks \$17,305<sup>[5]</sup>, \$1,310 over the median of \$15,995<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$6,950             |
| Middle half | \$13,298 – \$17,150 |
| Median ask  | \$15,995            |
| This car    | \$17,305            |

Same model year · 15 live listings · as of 27 Oct 2026

## OTHER 2016 VOLVO XC60 LISTINGS [5]

|                                |          |
|--------------------------------|----------|
| Komoka, ON · 129,073 km        | \$15,995 |
| Richmond, BC · 108,199 km      | \$19,995 |
| Quebec, QC · 187,357 km        | \$9,995  |
| North York, ON · 123,000 km    | \$16,900 |
| Charlottetown, PE · 139,735 km | \$13,599 |
| Winnipeg, MB · 140,534 km      | \$16,995 |

## §4 EVENTS

|             |                                                                                                                  |
|-------------|------------------------------------------------------------------------------------------------------------------|
| 2016        | Model year 2016 <sup>[1]</sup><br>Assembly plant Gent Plant, Belgium                                             |
| 2 Sep 2015  | Transport Canada recall 2015388 <sup>[2]</sup><br>Issued for the model year · Electrical                         |
| 28 Oct 2016 | Transport Canada recall 2016534 <sup>[2]</sup><br>Issued for the model year · Seats and restraints               |
| 30 Jun 2020 | Transport Canada recall 2020298 <sup>[2]</sup><br>Issued for the model year · Seats and restraints               |
| 22 Aug 2026 | Listed for sale, North Vancouver, BC <sup>[5]</sup><br>Jim Pattison Volvo Cars North Vancouver · asking \$17,305 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$17,305                                                           |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 15 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

