

2020 Volvo XC90 Inscription

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**YV4 A221L 8 L 1 596134**

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC90 · 2.0 L

CHECK 9

Computes

YEAR 10

2020

PLANT 11

Sweden

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	XC90	Drive	AWD
Trim	Inscription	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Sweden

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/volvo/xc90/2020

7 recalls listed by Transport Canada for this model year

High voltage

2025147 20 Mar 2025

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall only affects certain plug-in hybrid (PHEV) models. Safety Risk: A short circuit in the high-voltage battery can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Volvo advises not to charge your vehicle until the recall repairs have been completed. Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery module(s). The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module(s).

Brakes

2024628 23 Oct 2024

Issue: On certain vehicles, the rods connecting the brake pedal to the hydraulic brake unit may not have been assembled properly. As a result, the rods could loosen, and you may experience a change in brake pedal feel. This can cause reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the brake pedal pushrod screw.

Seats and restraints

2023649 7 Dec 2023

Issue: On certain vehicles, the bolts that attach the second-row seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the second-row seat belt buckle attachment bolts.



Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

Electrical

2021345 2 Jun 2021

Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.

Other

2021238 23 Apr 2021

Issue: On certain XC90 Excellence models, the rear seat control display may not work properly if the touch screen gets wet. This could cause the front passenger seat to move to the fully rearward position, even after you stop touching it. If the touch screen stays wet, you may not be able to move the seat forward again. Safety Risk: This could result in an injury for rear seat passengers. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealership to update the software for rear seat control display.

1 more on the model-year record, cardog.app/tools/recalls/volvo/xc90/2020

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$29,895^[5], \$85 under the median of \$29,980^[4].



Lowest ask	\$21,491
Middle half	\$26,990 – \$32,495
Median ask	\$29,980
This car	\$29,895

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2020 VOLVO XC90 LISTINGS ^[5]

Kingston, ON · 245,286 km	\$21,491
Aurora, ON · 155,472 km	\$23,988
Scarborough, ON · 97,890 km	\$29,895
Toronto, ON · 70,671 km	\$29,999
North York, ON · 116,493 km	\$24,880
Toronto, ON · 91,538 km	\$29,999



§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Sweden
13 Mar 2020	Transport Canada recall 2020099 ^[2] Issued for the model year · Brakes
23 Apr 2021	Transport Canada recall 2021238 ^[2] Issued for the model year · Other
2 Jun 2021	Transport Canada recall 2021345 ^[2] Issued for the model year · Electrical
20 Oct 2022	Transport Canada recall 2022595 ^[2] Issued for the model year · Visual system
7 Dec 2023	Transport Canada recall 2023649 ^[2] Issued for the model year · Seats and restraints
23 Oct 2024	Transport Canada recall 2024628 ^[2] Issued for the model year · Brakes
20 Mar 2025	Transport Canada recall 2025147 ^[2] Issued for the model year · High voltage
25 Oct 2026	Listed for sale, Scarborough, ON ^[5] Octane Auto Car Loans Toronto · asking \$29,895
28 Oct 2026	Listing last updated ^[5] asking \$29,895

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

