Register entry, as of 27 October 2026 Listed for sale Record ID 15f1af47c957

2016 Volvo XC90 SV42 Momentum

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV4	A22PK	0	G	1	014774
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Volvo Car Corporation	XC90 · 2.0 L	Computes	2016	Torslanda	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	XC90	Drive	AWD
Trim	SV42 Momentum	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Torslanda, Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc90/2016

8 recalls listed by Transport Canada for this model year

Seats and restraints

2023649 7 Dec 2023

Issue: On certain vehicles, the bolts that attach the second-row seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the second-row seat belt buckle attachment bolts.

Other

2021238 23 Apr 2021

Issue: On certain XC90 Excellence models, the rear seat control display may not work properly if the touch screen gets wet. This could cause the front passenger seat to move to the fully rearward position, even after you stop touching it. If the touch screen stays wet, you may not be able to move the seat forward again. Safety Risk: This could result in an injury for rear seat passengers. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealership to update the software for rear seat control display.

Engine

2019188 18 Apr 2019

Issue: On certain vehicles, the coolant bleeder hose could crack over time. This could allow coolant to leak on to the exhaust system. This could also cause a build-up of coolant in the insulation for the catalytic converter. Note: This condition could cause a low coolant level warning or a high temperature warning to display on the dash. Safety Risk: Coolant that contacts a hot exhaust system or that builds up over time in insulation could create a fire risk for a vehicle that is stopped or parked. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the coolant bleeder hose with an improved one.

Seats and restraints

2016534 28 Oct 2016

On certain vehicles, the front passenger seatbelt buckle stud may not have been punched correctly during manufacturing. This may cause a separation between the buckle and the seat belt bracket, which could result in the belt not adequately restraining the seat occupant in a crash, increasing the risk of injury and/or damage to property. Correction: Dealers will inspect the front passenger seat belt buckle stud, and replace the seatbelt buckle as necessary.

Airbag

2016469 23 Sep 2016

On certain vehicles, the air conditioner drain hose may leak into the passenger compartment due to incorrect installation during the manufacturing process. Over time, an accumulation of moisture in the passenger cabin could affect the SRS system (airbags), engine management systems and/or other systems. This could increase the risk of injury in the event of a crash and/or increase the risk of a crash causing injury and/or damage to property. Correction : Dealers will inspect the air conditioning drain hose to ensure correct installation and if necessary replace the drain hose.

Electrical

2016197 4 May 2016

Certain vehicles equipped with power-operated sunroof system may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 118 - Power-Operated Window, Partition and Roof Panel Systems. The switch could be more susceptible to inadvertent actuation, which could result in unintended auto-closure of the roof panel, contrary to the requirements of the standard and increase the risk of injury. Correction: Dealers will upgrade vehicle software that disables the auto-close function while depressing the sunroof switch.

2 more on the model-year record, cardog.app/tools/recalls/volvo/xc90/2016

> Listed for the model year, not checked against your VIN. Volvo confirms which apply.
> Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
> www.volvocars.com/en-ca/l/recall-information/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,495[5], $2,800 under the median of $18,295[4].



Lowest ask	$15,495
Middle half	$15,995 – $21,246
Median ask	$18,295
This car	$15,495

Same model year · 10 live listings · as of 27 Oct 2026

OTHER 2016 VOLVO XC90 LISTINGS [5]

Maple Ridge, BC · 144,000 km	$19,800
Abbotsford, BC · 151,000 km	$15,995
North York, ON · 146,699 km	$17,895
Etobicoke, ON · 208,522 km	$15,888
Toronto, ON · 167,000 km	$15,995
Fergus, ON · 137,000 km	$18,695

§4 EVENTS

2016	Model year 2016[1] Assembly plant Torslanda, Sweden
29 May 2015	Transport Canada recall 2015238[2] Issued for the model year · Airbag
5 Aug 2015	Transport Canada recall 2015355[2] Issued for the model year · Airbag
4 May 2016	Transport Canada recall 2016197[2] Issued for the model year · Electrical
23 Sep 2016	Transport Canada recall 2016469[2] Issued for the model year · Airbag
28 Oct 2016	Transport Canada recall 2016534[2] Issued for the model year · Seats and restraints
18 Apr 2019	Transport Canada recall 2019188[2] Issued for the model year · Engine
23 Apr 2021	Transport Canada recall 2021238[2] Issued for the model year · Other
7 Dec 2023	Transport Canada recall 2023649[2] Issued for the model year · Seats and restraints
1 Nov 2025	Listed for sale, Sherbrooke, QC[5] Les Inventaires MT Inc. · asking $15,495
27 Oct 2026	Listing last updated[5] asking $15,495

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.