Register entry, as of 28 October 2026 Listed for sale Record ID 40b1dd66c32a

# 2019 Volvo XC90 Inscription

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| YV4 | A22PL | 0 | K | 1 | 480495 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volvo Car Corporation | XC90 · 2.0 L | Computes | 2019 | Sweden | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 2.0 L, 4 cylinders |
| Make | Volvo | Fuel | Gasoline |
| Model | XC90 | Drive | AWD |
| Trim | Inscription | Maker | VOLVO CAR CORPORATION |
| Body | Sport Utility Vehicle | Plant | Sweden |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc90/2019

**6** recalls listed by Transport Canada for this model year

### Seats and restraints

2023649 7 Dec 2023

Issue: On certain vehicles, the bolts that attach the second-row seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the second-row seat belt buckle attachment bolts.

### Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

### Electrical

2021345 2 Jun 2021

Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.

### Other

2021238 23 Apr 2021

Issue: On certain XC90 Excellence models, the rear seat control display may not work properly if the touch screen gets wet. This could cause the front passenger seat to move to the fully rearward position, even after you stop touching it. If the touch screen stays wet, you may not be able to move the seat forward again. Safety Risk: This could result in an injury for rear seat passengers. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealership to update the software for rear seat control display.

### Brakes

2020099 13 Mar 2020

Issue: On certain vehicles, the automatic emergency braking system (AEB) may not apply the brakes automatically when it detects a possible collision. In addition, the system may not warn of a potential crash with a non-moving vehicle or object. Note: The regular brake system and all other functions in the vehicle are not affected by this problem. Safety Risk: The AEB system may not provide driver warnings and apply the brakes automatically to help avoid a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle software.

### Accessories

2018618 9 Nov 2018

On certain vehicles, the Telematics and Driver Support Systems may not function as designed due to a software error. In the event of a crash, this could mean that the Emergency Assist system would not alert Volvo and provide the GPS coordinates of the vehicle. This could create a risk of no response from emergency services. Correction: Dealers will update vehicle software.

> Listed for the model year, not checked against your VIN. Volvo confirms which apply.
> Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
> www.volvocars.com/en-ca/l/recall-information/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $19,995[5], $7,003 under the median of $26,998[4].

| | |
|---|---|
| Lowest ask | $19,995 |
| Middle half | $25,293 – $28,400 |
| Median ask | $26,998 |
| This car | $19,995 |

Same configuration · 11 live listings · as of 28 Oct 2026

OTHER 2019 VOLVO XC90 LISTINGS [5]

| | |
|---|---|
| Mississauga, ON · 131,312 km | $27,500 |
| Leamington, ON · 131,312 km | $27,500 |
| Essex, ON · 131,312 km | $27,500 |
| Prince George, BC · 95,570 km | $31,611 |
| Toronto, ON · 131,312 km | $27,500 |
| Burlington, ON · 93,000 km | $24,888 |

## §4 EVENTS

2019 Model year 2019[1]
Assembly plant Sweden

| | |
|---|---|
| 9 Nov 2018 | Transport Canada recall 2018618[2]<br>Issued for the model year · Accessories |
| 13 Mar 2020 | Transport Canada recall 2020099[2]<br>Issued for the model year · Brakes |
| 23 Apr 2021 | Transport Canada recall 2021238[2]<br>Issued for the model year · Other |
| 2 Jun 2021 | Transport Canada recall 2021345[2]<br>Issued for the model year · Electrical |
| 20 Oct 2022 | Transport Canada recall 2022595[2]<br>Issued for the model year · Visual system |
| 7 Dec 2023 | Transport Canada recall 2023649[2]<br>Issued for the model year · Seats and restraints |
| 2 Oct 2026 | Listed for sale, Toronto, ON[5]<br>Motorland Auto Sales Inc. · asking $19,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $19,995 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.