Register entry, as of 27 October 2026 Listed for sale Record ID faf78d40df37

2021 Volvo XC90 R-Design

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV4	A22PM	5	M	1	720491
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volvo Car Corporation	XC90 · 2.0 L	Computes	2021	Sweden	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	XC90	Drive	AWD
Trim	R-Design	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc90/2021

5 recalls listed by Transport Canada for this model year

High voltage

2025147 20 Mar 2025

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall only affects certain plug-in hybrid (PHEV) models. Safety Risk: A short circuit in the high-voltage battery can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Volvo advises not to charge your vehicle until the recall repairs have been completed. Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery module(s). The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module(s).

Seats and restraints

2023649 7 Dec 2023

Issue: On certain vehicles, the bolts that attach the second-row seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the second-row seat belt buckle attachment bolts.

Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

Seats and restraints

2021540 1 Sep 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Airbag

2021003 7 Jan 2021

Issue: On certain vehicles, the screws that attach the control unit for the supplemental restraint system (SRS) may not have been properly tightened. As a result, the SRS control unit may not work properly and could come loose in a crash. If this happens, the seat belt pretensioner(s), airbag systems and high-voltage battery disconnect may not work correctly. Note: This problem may cause the SRS warning lamp to turn on and a "Service Urgent" message may display in the instrument cluster. Safety Risk: A seat belt pretensioner, airbag system or high-voltage battery disconnect that does not work properly in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the mounting screws for the SRS control unit. They will be tightened, if necessary.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.
Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
www.volvocars.com/en-ca/l/recall-information/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $35,995[5], $2,739 under the median of $38,734[4].

Lowest ask	$27,985
Middle half	$33,490 – $40,665
Median ask	$38,734
This car	$35,995

Same model year · 10 live listings · as of 27 Oct 2026

OTHER 2021 VOLVO XC90 LISTINGS [5]

Verdun, QC · 77,806 km	$39,995
Montréal, QC · 111,809 km	$32,980
Richmond, BC · 73,896 km	$32,995
North York, ON · 99,451 km	$37,479
Montréal, QC · 87,833 km	$41,474
North York, ON · 123,636 km	$27,985

§4 EVENTS

2021	Model year 2021[1] Assembly plant Sweden
7 Jan 2021	Transport Canada recall 2021003[2] Issued for the model year · Airbag

1 Sep 2021	Transport Canada recall 2021540[2] Issued for the model year · Seats and restraints
20 Oct 2022	Transport Canada recall 2022595[2] Issued for the model year · Visual system
7 Dec 2023	Transport Canada recall 2023649[2] Issued for the model year · Seats and restraints
20 Mar 2025	Transport Canada recall 2025147[2] Issued for the model year · High voltage
4 Sep 2026	Listed for sale, Mississauga, ON[5] Automotive Sales Depot · asking $35,995
27 Oct 2026	Listing last updated[5] asking $35,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.