

Register entry, as of 27 October 2026

Listed for sale

Record ID 18a1a1adba53

# 2018 Volvo XC60 Momentum

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**YV4 A22RK 0 J 1 043101**

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC60 · 2.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Torslanda

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                       |
|------------|-----------------------|--------|-----------------------|
| Model year | 2018                  | Engine | 2.0 L, 4 cylinders    |
| Make       | Volvo                 | Fuel   | Gasoline              |
| Model      | XC60                  | Drive  | AWD                   |
| Trim       | Momentum              | Maker  | VOLVO CAR CORPORATION |
| Body       | Sport Utility Vehicle | Plant  | Torslanda, Sweden     |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volvo/xc60/2018](https://cardog.app/tools/recalls/volvo/xc60/2018)

## 3 recalls listed by Transport Canada for this model year

### Visual system

2020390 25 Aug 2020

Issue: On certain vehicles, the nuts that attach the windshield wiper arms may not have been tightened properly. This could cause the wipers to slip and not clear the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to tighten the nuts on the windshield wiper arms.

### Structure

2019030 21 Jan 2019

Issue: On certain vehicles equipped with a power operated tailgate, the tailgate lifting arms could freeze and fail. This could create noise and cause the tailgate to stop working. It could also cause the tailgate lifting arms to separate. Safety Risk: If the tailgate arms separate, a spring may be projected rearward and create a risk of injury. Corrective Action: The company will notify owners by mail. Owners will be advised to take their vehicle to a dealer for replacement of the tailgate lifting arms.

### Accessories

2018618 9 Nov 2018

On certain vehicles, the Telematics and Driver Support Systems may not function as designed due to a software error. In the event of a crash, this could mean that the Emergency Assist system would not alert Volvo and provide the GPS coordinates of the vehicle. This could create a risk of no response from emergency services. Correction: Dealers will update vehicle software.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.


[www.volvocars.com/en-ca/l/recall-information/](https://www.volvocars.com/en-ca/l/recall-information/)



United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$17,500<sup>[5]</sup>, \$2,490 under the median of \$19,990<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$14,980            |
| Middle half | \$17,500 – \$20,995 |
| Median ask  | \$19,990            |
| This car    | \$17,500            |

Same model year · 13 live listings · as of 27 Oct 2026

#### OTHER 2018 VOLVO XC60 LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Wetaskiwin, AB · 141,975 km  | \$19,990 |
| Fredericton, NB · 129,129 km | \$21,494 |
| Levis, QC · 154,062 km       | \$16,595 |
| Toronto, ON · 129,099 km     | \$17,750 |
| Langford, BC · 129,969 km    | \$20,339 |
| Courtenay, BC · 129,969 km   | \$21,895 |

### §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2018        | Model year 2018 <sup>[1]</sup><br>Assembly plant Torslanda, Sweden                          |
| 9 Nov 2018  | Transport Canada recall 2018618 <sup>[2]</sup><br>Issued for the model year · Accessories   |
| 21 Jan 2019 | Transport Canada recall 2019030 <sup>[2]</sup><br>Issued for the model year · Structure     |
| 25 Aug 2020 | Transport Canada recall 2020390 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Fergus, ON <sup>[5]</sup><br>MELITA AUTO SALES · asking \$17,500           |

### §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

#### SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 13 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

