Register entry, as of 29 October 2026 Listed for sale Record ID e3bf5050bd88

2022 Volvo XC90 Momentum (excl S60)

2.0 L, 4 cylinders · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

YV4	BR0CK	2	N	1	784353
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volvo Car Corporation	XC90 · 2.0 L	Computes	2022	Sweden	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Electric
Model	XC90	Drive	Not in the decode
Trim	Momentum (excl S60)	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc90/2022

4 recalls listed by Transport Canada for this model year

Brakes

2025319 12 Jun 2025

Issue: Under certain conditions, a software problem could cause a loss of brakes. Note: This recall only affects plug-in hybrid (PHEV) and electric vehicles. Safety Risk: A loss of brakes can increase the risk of a crash. Corrective Actions: To reduce the safety risk, Volvo recommends not to use the "B" or "One Pedal Drive" drive modes until the recall repairs are completed. Volvo will notify owners by mail and advise you to take your vehicles to a dealership to update the brake control module software.

High voltage

2025147 20 Mar 2025

Issue: On certain vehicles, there could be a problem inside the high-voltage battery. As a result, the battery modules could overheat and short circuit. Note: This recall only affects certain plug-in hybrid (PHEV) models. Safety Risk: A short circuit in the high-voltage battery can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Volvo advises not to charge your vehicle until the recall repairs have been completed. Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery module(s). The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module(s).

Seats and restraints

2023649 7 Dec 2023

Issue: On certain vehicles, the bolts that attach the second-row seat belt buckles may not have been properly tightened. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the second-row seat belt buckle attachment bolts.

Visual system

2022595 20 Oct 2022

Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.
Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
www.volvocars.com/en-ca/l/recall-information/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $43,595[5], $695 over the median of $42,900[4].

Lowest ask	$32,988
Middle half	$38,988 – $43,995
Median ask	$42,900
This car	$43,595

Same model year · 50 live listings · as of 29 Oct 2026

OTHER 2022 VOLVO XC90 LISTINGS [5]

Lévis, QC · 109,500 km	$32,988
North Vancouver, BC · 78,510 km	$42,905
Waterloo, ON · 77,073 km	$43,995
Ajax, ON · 71,055 km	$42,895
Kingston, ON · 82,890 km	$42,600
Edmonton, AB · 61,206 km	$46,933

§4 EVENTS

2022	Model year 2022[1] Assembly plant Sweden
20 Oct 2022	Transport Canada recall 2022595[2] Issued for the model year · Visual system
7 Dec 2023	Transport Canada recall 2023649[2] Issued for the model year · Seats and restraints
20 Mar 2025	Transport Canada recall 2025147[2] Issued for the model year · High voltage
12 Jun 2025	Transport Canada recall 2025319[2] Issued for the model year · Brakes

4 Nov 2025	Listed for sale, Surrey, BC[5] Jim Pattison Volvo Cars Surrey · asking $43,595
28 Oct 2026	Listing last updated[5] asking $43,595

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 50 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.