Register entry, as of 27 October 2026 Listed for sale Record ID f8d8c19c7c2a

2023 Dodge HORNET GT

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

ZAC	NDFAN	7	P	3	A01374
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · STELLANTIS EURO…	HORNET · 2.0 L	Computes	2023	Naples	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Dodge	Fuel	Gasoline
Model	HORNET	Drive	Not in the decode
Trim	GT	Maker	STELLANTIS EUROPE SPA
Body	Sport Utility Vehicle	Plant	Naples, Pomigliano, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/hornet/2023

10 recalls listed by Transport Canada for this model year

Seats and restraints

2026381 6 Aug 2026

Issue: On certain vehicles, the rear left and right outboard seat belts could become twisted and may not retract correctly. As a result, the seat belts may not work properly in a crash. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the rear outboard seat belt retractors.

Lights and instruments

2026315 30 Jun 2026

Issue: On certain vehicles, the recall repairs completed by an FCA dealer during recall A9C (Transport Canada recall no. 2025-590) may not have been done correctly. As a result, a second repair is required. On certain vehicles, a software problem could cause the daytime running lights (DRLs) not to turn on. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This recall replaces Transport Canada recall no. 2025-590. Safety Risk: DRLs that don't turn on could reduce visibility and make the vehicle less visible to others. These issues could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the vehicle software.

Lights and instruments

2025590 28 Oct 2025

Issue: On certain vehicles, a software problem could cause the daytime running lights (DRLs) not to turn on. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: DRLs that don't turn on could reduce visibility and make the vehicle less visible to others. These issues could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the vehicle software.

Visual system

2025204 15 Apr 2025

Issue: On certain vehicles, the rearview camera may not have been manufactured properly and/or there could be a problem in the rearview camera software. As a result, the rearview camera image may not display. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the rearview camera software. For certain vehicles, the dealer will also replace the radio assembly.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Label

2024177 19 Mar 2024

Issue: On certain vehicles, the compliance label doesn't list the gross vehicle weight rating (GVWR), the tire size or the rim size. This could lead to overloading of the vehicle. Additionally, when the rims and tires are replaced, the wrong rims and/or tires could be installed. Both issues could cause poor handling or a tire failure. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to install a corrected compliance label.

4 more on the model-year record, cardog.app/tools/recalls/dodge/hornet/2023

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,999[5], $4,000 under the median of $23,999[4].

Lowest ask	$19,999
Middle half	$22,574 – $25,744
Median ask	$23,999
This car	$19,999

Same configuration · 23 live listings · as of 27 Oct 2026

OTHER 2023 DODGE HORNET LISTINGS [5]

Grande Prairie, AB · 37,237 km	$23,609
Carleton Place, ON · 65,492 km	$22,491
Simcoe, ON · 8,322 km	$27,495
Ingersoll, ON · 100,281 km	$21,954
Simcoe, ON · 8,322 km	$27,495
Laval, QC · 35,700 km	$21,999

§4 EVENTS

2023	Model year 2023[1] Assembly plant Naples, Pomigliano, Italy
7 Sep 2023	Transport Canada recall 2023501[2] Issued for the model year · High voltage
17 Oct 2023	Transport Canada recall 2023558[2] Issued for the model year · Lights and instruments
12 Dec 2023	Transport Canada recall 2023654[2] Issued for the model year · Label
5 Mar 2024	Transport Canada recall 2024147[2] Issued for the model year · Label
19 Mar 2024	Transport Canada recall 2024177[2] Issued for the model year · Label
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
15 Apr 2025	Transport Canada recall 2025204[2] Issued for the model year · Visual system
28 Oct 2025	Transport Canada recall 2025590[2] Issued for the model year · Lights and instruments
21 Jun 2026	Listed for sale, Mercier, QC[5] Le Prix Duclos · asking $19,999
30 Jun 2026	Transport Canada recall 2026315[2] Issued for the model year · Lights and instruments
6 Aug 2026	Transport Canada recall 2026381[2] Issued for the model year · Seats and restraints
14 Sep 2026	Window sticker collected[6] Issued by STELLANTIS
27 Oct 2026	Listing last updated[5] asking $19,999

§5 DOCUMENTS [6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 23 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026
[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.