Register entry, as of 26 October 2026 Listed for sale Record ID a7aa3f505725

2016 Maserati Ghibli

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

ZAM	57RTA	1	G	1	176226
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Maserati S.P.A.	Ghibli · 3.0 L	Computes	2016	Grugliasco	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.0 L, 6 cylinders
Make	Maserati	Fuel	Gasoline
Model	Ghibli	Drive	AWD
Trim	Not in the decode	Maker	MASERATI S.P.A.
Body	Sedan	Plant	Grugliasco, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/maserati/ghibli/2016

4 recalls listed by Transport Canada for this model year

Label

2022708 13 Dec 2022

Issue: On certain vehicles, the airbag warning labels are located on the headliner under the sun visors. Canadian regulations require information about the airbag system to be provided on both sides of the sun visor. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Maserati has made changes to ensure that all new vehicles have the airbag warning labels installed correctly.

Seats and restraints

2017033 20 Jan 2017

On certain vehicles, the seat wiring harness layout may have been routed incorrectly during manufacturing. Through normal seat adjustment, this could cause the seat wiring harness to rub against metal points on the seat/seat frame assembly. Over time, this could lead to an inoperative seat adjustment system, and in some cases could result in an electrical short to ground between the seat wiring harness and the seat adjustment motor assembly, which could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect routing and will secure and protect the seat wiring harness, and if necessary, install a new seat wiring harness.

Suspension

2016195 3 May 2016

On certain vehicles, a bolt that attaches the rear tie-rod to the hub carrier assembly may not have been torqued to specification. This could cause the bolt to loosen, which could result in noise from the rear of the vehicle. Over time, this could lead to separation of the tie-rod from the hub carrier, affecting steering control and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect tie-rod to hub carrier attaching bolts and will repair as necessary.

Accessories

2016097 29 Feb 2016

On certain vehicles, the driver side floor mat anchors could break over time which could allow the floor mat to slide forward and potentially allowing the accelerator to become stuck in the wide open position. A fully depressed accelerator pedal may result in very high vehicle speeds and make it difficult to slow or stop the vehicle. This could result in a crash causing injury and/or damage to property. Correction: Dealers will replace the driver side floor mat and possibly the accelerator pedal cover.

> Listed for the model year, not checked against your VIN. Maserati confirms which apply.
> Check your VIN with Maserati Canada or call a Maserati dealer with your VIN.
> www.maserati.com/ca/en/ownership/service-assistance/recall-information

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,900[5], $1,000 over the median of $23,900[4].

Lowest ask	$14,988
Middle half	$20,721 – $25,721
Median ask	$23,900
This car	$24,900

Same model year · 6 live listings · as of 26 Oct 2026

OTHER 2016 MASERATI GHIBLI LISTINGS [5]

London, ON · 60,685 km	$34,940
Ancaster, ON · 68,000 km	$25,995
Toronto, ON · 0 km	$14,988
Richmond, BC · 99,937 km	$19,995
North York, ON · 88,943 km	$22,900

§4 EVENTS

2016	Model year 2016[1] Assembly plant Grugliasco, Italy
29 Feb 2016	Transport Canada recall 2016097[2] Issued for the model year · Accessories
3 May 2016	Transport Canada recall 2016195[2] Issued for the model year · Suspension
20 Jan 2017	Transport Canada recall 2017033[2] Issued for the model year · Seats and restraints
13 Dec 2022	Transport Canada recall 2022708[2] Issued for the model year · Label
15 Sep 2026	Listed for sale, Vancouver, BC[5] SMS Motors · asking $24,900

26 Oct 2026 Listing last updated[5]
asking $24,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.