

Register entry, as of 29 October 2026

Listed for sale

Record ID 4b93652a862f

2014 Maserati Ghibli

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

ZAM 57RTA 7 E 1 111541

WMI 1-3

Maserati S.P.A.

DESCRIPTOR 4-8

Ghibli · 3.0 L

CHECK 9

Computes

YEAR 10

2014

PLANT 11

Grugliasco

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.0 L, 6 cylinders
Make	Maserati	Fuel	Gasoline
Model	Ghibli	Drive	AWD
Trim	Not in the decode	Maker	MASERATI S.P.A.
Body	Sedan	Plant	Grugliasco, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/maserati/ghibli/2014

7 recalls listed by Transport Canada for this model year

Label	2022708 13 Dec 2022
Issue: On certain vehicles, the airbag warning labels are located on the headliner under the sun visors. Canadian regulations require information about the airbag system to be provided on both sides of the sun visor. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Maserati has made changes to ensure that all new vehicles have the airbag warning labels installed correctly.	
Fuel system	2018701 13 Dec 2018
On certain vehicles, the fuel lines may weep or leak fuel due to an error in the assembly process. Fuel leaks may potentially occur at any location along the fuel line due to the introduction of foreign particles between the metal fuel line and plastic fuel line during the connection process. This could cause scratches on the plastic fuel line portion, and over time can increase the risk of an underhood fire causing injury and/or property damage. Correction: Dealers will install a new fuel line. Note: This is an expansion of Recall 2017-032.	
Seats and restraints	2017033 20 Jan 2017
On certain vehicles, the seat wiring harness layout may have been routed incorrectly during manufacturing. Through normal seat adjustment, this could cause the seat wiring harness to rub against metal points on the seat/seat frame assembly. Over time, this could lead to an inoperative seat adjustment system, and in some cases could result in an electrical short to ground between the seat wiring harness and the seat adjustment motor assembly, which could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect routing and will secure and protect the seat wiring harness, and if necessary, install a new seat wiring harness.	



Fuel system

2017032 20 Jan 2017

On certain vehicles, the fuel lines may weep or leak fuel due to an error in the assembly process. Fuel leaks may potentially occur at any location along the fuel line due to the introduction of foreign particles between the metal fuel line and plastic fuel line during the connection process. This could cause scratches on the plastic fuel line portion, and over time can increase the risk of an underhood fire causing injury and/or property damage. Correction: Dealers will install a new fuel line.

Powertrain

2016293 8 Jun 2016

On certain vehicles, the gear shift position indicators and warnings may not be sufficient to deter drivers from exiting the vehicle when the transmission is inadvertently left in a gear other than “Park”. If this occurs and the driver exits the vehicle with the engine running and the parking brake has not been set, unintended vehicle movement can result, increasing the risk of injury and/or a crash. Correction: Dealers will update vehicle software to include additional features to protect against driver error.

Suspension

2016195 3 May 2016

On certain vehicles, a bolt that attaches the rear tie-rod to the hub carrier assembly may not have been torqued to specification. This could cause the bolt to loosen, which could result in noise from the rear of the vehicle. Over time, this could lead to separation of the tie-rod from the hub carrier, affecting steering control and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect tie-rod to hub carrier attaching bolts and will repair as necessary.


1 more on the model-year record, cardog.app/tools/recalls/maserati/ghibli/2014

Listed for the model year, not checked against your VIN. Maserati confirms which apply.
Check your VIN with Maserati Canada or call a Maserati dealer with your VIN.
www.maserati.com/ca/en/ownership/service-assistance/recall-information

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$18,950^[5], \$25 over the median of \$18,925^[4].



Lowest ask	\$18,777
Middle half	\$18,869 – \$19,212
Median ask	\$18,925
This car	\$18,950

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2014 MASERATI GHIBLI LISTINGS [5]

Laval, QC · 139,987 km	\$18,777
Oshawa, ON · 171,970 km	\$19,999
Toronto, ON · 74,541 km	\$18,900

§4 EVENTS

2014 Model year 2014^[1]
Assembly plant Grugliasco, Italy

29 Feb 2016 Transport Canada recall 2016097^[2]
Issued for the model year · Accessories



3 May 2016	Transport Canada recall 2016195 ^[2] Issued for the model year · Suspension
8 Jun 2016	Transport Canada recall 2016293 ^[2] Issued for the model year · Powertrain
20 Jan 2017	Transport Canada recall 2017033 ^[2] Issued for the model year · Seats and restraints
20 Jan 2017	Transport Canada recall 2017032 ^[2] Issued for the model year · Fuel system
13 Dec 2018	Transport Canada recall 2018701 ^[2] Issued for the model year · Fuel system
13 Dec 2022	Transport Canada recall 2022708 ^[2] Issued for the model year · Label
28 Oct 2026	Listed for sale, Hamilton, ON ^[5] OTTO'S AUTO SALES · asking \$18,950
29 Oct 2026	Listing last updated ^[5] asking \$18,950

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

