Register entry, as of 26 October 2026 Listed for sale Record ID 17f1aa12a2fc

2017 Maserati Ghibli Luxury

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

ZAM	57RTL	9	H	1	233694
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Maserati S.P.A.	Ghibli · 3.0 L	Computes	2017	Grugliasco	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.0 L, 6 cylinders
Make	Maserati	Fuel	Gasoline
Model	Ghibli	Drive	AWD
Trim	Luxury	Maker	MASERATI S.P.A.
Body	Sedan	Plant	Grugliasco, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/maserati/ghibli/2017

5 recalls listed by Transport Canada for this model year

Label — 2022708 — 13 Dec 2022

Issue: On certain vehicles, the airbag warning labels are located on the headliner under the sun visors. Canadian regulations require information about the airbag system to be provided on both sides of the sun visor. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Maserati has made changes to ensure that all new vehicles have the airbag warning labels installed correctly.

Powertrain — 2018134 — 15 Mar 2018

On certain vehicles, the engine control module software may put the vehicles in neutral or park or shut the engine off when moving at low speeds. Depending on traffic conditions, an unintentional engine shut-down could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the engine control module.

Seats and restraints — 2017033 — 20 Jan 2017

On certain vehicles, the seat wiring harness layout may have been routed incorrectly during manufacturing. Through normal seat adjustment, this could cause the seat wiring harness to rub against metal points on the seat/seat frame assembly. Over time, this could lead to an inoperative seat adjustment system, and in some cases could result in an electrical short to ground between the seat wiring harness and the seat adjustment motor assembly, which could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect routing and will secure and protect the seat wiring harness, and if necessary, install a new seat wiring harness.

Powertrain

2016588 23 Nov 2016

On certain vehicles, the rear differential unit pinion nut may not have been tightened correctly during manufacturing. If the pinion nut loosens, it could cause noise, vibration, reduced gear and bearing life, and a differential fluid leak at the pinion seal. In the worst case, the rear wheels could lock up while the vehicle is in motion, causing a loss of vehicle control, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will check the torque of the rear differential unit pinion nut and, if necessary, replace the rear differential unit.

Accessories

2016572 16 Nov 2016

On certain vehicles, the Entertainment-Telematics Module (ETM) may become inoperative when subjected to temperatures below Zero degrees Celsius. If this occurs, the backup camera image would not be displayed in the ETM which could increase the risk of a crash causing injury and/or damage to property while reversing. Correction: Dealers update the Entertainment-Telematics Module.

> Listed for the model year, not checked against your VIN. Maserati confirms which apply.
> Check your VIN with Maserati Canada or call a Maserati dealer with your VIN.
> www.maserati.com/ca/en/ownership/service-assistance/recall-information

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,988[5], $2,008 over the median of $23,980[4].

Lowest ask	$15,888
Middle half	$20,950 – $25,944
Median ask	$23,980
This car	$25,988

Same model year · 11 live listings · as of 26 Oct 2026

OTHER 2017 MASERATI GHIBLI LISTINGS [5]

North York, ON · 101,000 km	$21,999
Toronto, ON · 171,000 km	$15,988
Toronto, ON · 79,800 km	$26,988
North York, ON · 46,000 km	$30,888
Vaughan, ON · 88,460 km	$25,888
Surrey, BC · 111,950 km	$19,900

§4 EVENTS

2017	Model year 2017[1] Assembly plant Grugliasco, Italy
16 Nov 2016	Transport Canada recall 2016572[2] Issued for the model year · Accessories
23 Nov 2016	Transport Canada recall 2016588[2] Issued for the model year · Powertrain
20 Jan 2017	Transport Canada recall 2017033[2] Issued for the model year · Seats and restraints

15 Mar 2018	Transport Canada recall 2018134[2] Issued for the model year · Powertrain
13 Dec 2022	Transport Canada recall 2022708[2] Issued for the model year · Label
4 Sep 2026	Listed for sale, Toronto, ON[5] Bell Auto Inc. · asking $25,988
26 Oct 2026	Listing last updated[5] asking $25,988

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.