Register entry, as of 26 October 2026 Listed for sale Record ID 5e22143e6163

# 2018 Alfa Romeo Stelvio

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| ZAS | FAKBN | 1 | J | 7 | B92024 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Alfa Romeo S.P.A. | Stelvio · 2.0 L | Computes | 2018 | Piedimonte San Germano | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 2.0 L, 4 cylinders |
| Make | Alfa Romeo | Fuel | Gasoline |
| Model | Stelvio | Drive | AWD |
| Trim | Not in the decode | Maker | ALFA ROMEO S.P.A. |
| Body | Sport Utility Vehicle | Plant | Piedimonte San Germano, Lazio, Italy |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/alfa-romeo/stelvio/2018

**12** recalls listed by Transport Canada for this model year

### Fuel system

2025463 9 Sep 2025

Issue: On certain vehicles, the fuel delivery module could fail and cause a loss of engine power while driving. Note: This problem could cause the malfunction indicator light to turn on. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Seats and restraints

2024390 3 Jul 2024

Issue: On certain vehicles, the connector for the driver and/or passenger-front seat belt buckle sensor(s) could fail and cause the seat airbag(s) to deploy with too much force. Note: This problem would cause the airbag warning light to display on the instrument panel or the seat belt reminder chime and warning light to stay on, even if you're buckled. Safety Risk: An airbag that deploys with too much force could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the connector for the driver and/or passenger-front seat belt buckle sensor(s).

### Brakes

2023312 30 May 2023

Issue: In certain situations, the braking system could apply too much force to the brake rotors. If this happens, the brake rotors could crack and suddenly cause reduced braking. Note: This recall only affects vehicles equipped with carbon ceramic matrix brakes. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the brake system module (BSM) software.

### Fuel system

2019366 25 Jul 2019

Issue: On certain vehicles, the fuel gauge may display the wrong fuel level (higher) when parked on a slope of at least 10 degrees. This could cause a driver to believe there is fuel when the tank is empty. In the worst case scenario, the vehicle could unexpectedly run out of fuel and stall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the body control module software.

### Powertrain

2019110 1 Mar 2019

Issue: Under specific driving conditions, the driver may not be able to cancel the adaptive cruise control (ACC) setting. Safety Risk: If the driver does not shift to neutral or apply the brakes to stop the vehicle, this can cause a crash without warning. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the brake system software. Drivers should not use the adaptive cruise control feature until this update is completed.

6 more on the model-year record, cardog.app/tools/recalls/alfa-romeo/stelvio/2018

> Listed for the model year, not checked against your VIN. Alfa Romeo confirms which apply.
> Check your VIN with Mopar Canada or call a Alfa Romeo dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $22,995[5], $3,597 over the median of $19,398[4].




| | |
|---|---|
| Lowest ask | $13,950 |
| Middle half | $17,989 – $21,490 |
| Median ask | $19,398 |
| This car | $22,995 |

Same model year · 18 live listings · as of 26 Oct 2026

OTHER 2018 ALFA ROMEO STELVIO LISTINGS [5]

| | |
|---|---|
| Mississauga, ON · 90,562 km | $17,995 |
| Edmonton, AB · 85,671 km | $24,500 |
| Montreal, QC · 91,663 km | $17,987 |
| Montreal, QC · 72,336 km | $22,987 |
| Barrie, ON · 98,660 km | $18,886 |
| Quebec, QC · 149,500 km | $14,990 |

## §4 EVENTS

2018 Model year 2018[1]
Assembly plant Piedimonte San Germano, Lazio, Italy

| | |
|---|---|
| 21 Dec 2017 | Transport Canada recall 2017661[2]<br>Issued for the model year · Brakes |
| 7 Mar 2018 | Transport Canada recall 2018116[2]<br>Issued for the model year · Visual system |
| 29 Mar 2018 | Transport Canada recall 2018151[2]<br>Issued for the model year · Visual system |
| 29 Mar 2018 | Transport Canada recall 2018150[2]<br>Issued for the model year · Electrical |
| 14 Sep 2018 | Transport Canada recall 2018506[2]<br>Issued for the model year · Engine |
| 14 Sep 2018 | Transport Canada recall 2018505[2]<br>Issued for the model year · Engine |
| 1 Mar 2019 | Transport Canada recall 2019110[2]<br>Issued for the model year · Powertrain |
| 25 Jul 2019 | Transport Canada recall 2019366[2]<br>Issued for the model year · Fuel system |
| 30 May 2023 | Transport Canada recall 2023312[2]<br>Issued for the model year · Brakes |
| 3 Jul 2024 | Transport Canada recall 2024390[2]<br>Issued for the model year · Seats and restraints |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 9 Sep 2025 | Transport Canada recall 2025463[2]<br>Issued for the model year · Fuel system |
| 22 Apr 2026 | Listed for sale, Calgary, AB[5]<br>BSPACE AUTOMOTIVE · asking $22,995 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $22,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 18 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.