Register entry, as of 26 October 2026 Listed for sale Record ID 7a9056042a41

2021 Alfa Romeo Stelvio

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

ZAS	PAKBN	5	M	7	D16689
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Alfa Romeo S.P.A.	Stelvio · 2.0 L	Computes	2021	Piedimonte San Germano	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Alfa Romeo	Fuel	Gasoline
Model	Stelvio	Drive	AWD
Trim	Not in the decode	Maker	ALFA ROMEO S.P.A.
Body	Sport Utility Vehicle	Plant	Piedimonte San Germano, Frosinone, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/alfa-romeo/stelvio/2021

7 recalls listed by Transport Canada for this model year

Visual system

2025533 7 Oct 2025

Issue: On certain vehicles, the radio may not have been manufactured properly and/or there could be a problem with the radio software. As a result, the rearview camera image may not display correctly or at all. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the radio. The dealer will also update the radio software, as necessary.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Seats and restraints

2024390 3 Jul 2024

Issue: On certain vehicles, the connector for the driver and/or passenger-front seat belt buckle sensor(s) could fail and cause the seat airbag(s) to deploy with too much force. Note: This problem would cause the airbag warning light to display on the instrument panel or the seat belt reminder chime and warning light to stay on, even if you're buckled. Safety Risk: An airbag that deploys with too much force could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the connector for the driver and/or passenger-front seat belt buckle sensor(s).

Label

2024379 3 Jul 2024

Issue: On certain vehicles, the tire and loading information label and/or the compliance label may list incorrect tire size and/or tire pressure information. This could lead you to inflate the tires incorrectly and/or install the wrong tires. These errors could lead to poor handling and/or a tire failure. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the tire and loading information label and/or the compliance label.

Fuel system

2021700 15 Nov 2021

Issue: On certain vehicles, the housing for the fuel line sensor could crack and leak fuel. If this happens, the engine can stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Additionally, a fuel leak can create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the build code on the fuel line sensor housing and replace it, as required.

Brakes

2021264 4 May 2021

Issue: On a small number of vehicles, there may be a problem with the antilock brake system (ABS) hydraulic control unit. During hard braking, this could cause a sudden loss of brake assist and ABS braking. If this happens, there will be an increase in brake pedal effort that is required to stop the vehicle. Safety Risk: A sudden increase in brake pedal force and a loss of ABS braking could lead to an increase in stopping distance. This could increase the risk of a crash. Corrective Actions: Fiat Chrysler Automobiles (FCA) will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS hydraulic control unit.

1 more on the model-year record, cardog.app/tools/recalls/alfa-romeo/stelvio/2021

> Listed for the model year, not checked against your VIN. Alfa Romeo confirms which apply.
> Check your VIN with Mopar Canada or call a Alfa Romeo dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,990[5], the median[4].

Lowest ask	$21,990
Middle half	$24,879 – $28,990
Median ask	$26,990
This car	$26,990

Same configuration · 21 live listings · as of 26 Oct 2026

OTHER 2021 ALFA ROMEO STELVIO LISTINGS [5]

Chatham, ON · 66,592 km	$24,879
Milton, ON · 115,692 km	$25,995
Milton, ON · 91,050 km	$24,999
London, ON · 64,364 km	$42,940
Edmonton, AB · 61,989 km	$33,995
Trois-Rivières, QC · 74,771 km	$25,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Piedimonte San Germano, Frosinone, Italy
30 Mar 2021	Transport Canada recall 2021191[2] Issued for the model year · Airbag
4 May 2021	Transport Canada recall 2021264[2] Issued for the model year · Brakes
15 Nov 2021	Transport Canada recall 2021700[2] Issued for the model year · Fuel system
3 Jul 2024	Transport Canada recall 2024390[2] Issued for the model year · Seats and restraints
3 Jul 2024	Transport Canada recall 2024379[2] Issued for the model year · Label
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
7 Oct 2025	Transport Canada recall 2025533[2] Issued for the model year · Visual system
30 Nov 2025	Listed for sale, Vancouver, BC[5] Alfa Romeo Of Vancouver · asking $26,990
26 Oct 2026	Listing last updated[5] asking $26,990

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 21 live listings, as of 26 Oct 2026

[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.